

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NRM2002843138
District RP	
Facility ID	
Application ID	

## Release Notification

Responsible Party

6O3SG-191211-C-1410

Responsible Party Devon Energy Production Company	OGRID 6137
Contact Name Amanda T. Davis	Contact Telephone 575-748-0176
Contact email amanda.davis@dvn.com	Incident # (assigned by OCD)
Contact mailing address 6488 Seven Rivers HWY	

### Location of Release Source

Latitude 32.66301 Longitude -103.8837  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Sirius 17 Fed #6H	Site Type Oil
Date Release Discovered 11/24/2019	API# (if applicable) 30-015-41761

Unit Letter	Section	Township	Range	County
H	17	19S	31E	Eddy

Surface Owner:  State  Federal  Tribal  Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 3	Volume Recovered (bbls) .5
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 10	Volume Recovered (bbls) 1.5
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release 1" nipple of pumping T developed a pin hole leak causing fluid release. All fluid stayed on location. See attachment for spill area calculation.

Incident ID	NRM2002843138
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:  <b>This spill was not in containment.</b>
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>Kendra DeHoyos</u> Title: <u>EHS Associate</u> Signature: <u><i>Kendra DeHoyos</i></u> Date: <u>12/03/2019</u> email: <u>kendra.dehoyos@dvn.com</u> Telephone: <u>575-748-3371</u>
<b><u>OCD Only</u></b> Received by: <u>Ramona Marcus</u> Date: <u>1/28/2020</u>

**Spill Volume(Bbls) Calculator**

*Inputs in blue , Outputs in red*

**Contaminated Soil measurement**

Area (square feet)	Depth(inches)
<u>2442.37</u>	<u>0.330</u>
Cubic Feet of Soil Impacted	<u>67.165</u>
Barrels of Soil Impacted	<u>11.97</u>
Soil Type	Clay/Sand
Barrels of Oil Assuming 100% Saturation	<u>1.80</u>
Saturation	Fluid present with shovel/backhoe
Estimated Barrels of Oil Released	1.80
<b>Free Standing Fluid Only</b>	
Area (square feet)	Depth(inches)
<u>2442.37</u>	<u>0.330</u>
Standing fluid	<u>11.972</u>
<b>Total fluids spilled</b>	<b><u>13.768</u></b>

NRM2002843138

Sirius 17 Fed 6H

NRM2002843138

Perimeter: 370.716 ft

Area: 2442.375 ft<sup>2</sup>

Group name : (32.6629904, -103.8837160)

