Littrell, Kyle Eads, Cristina, EMNRD [EXT] RE: Muy Wayno Frac Pond Friday, February 21, 2020 12:40:52 PM Attachn

image002.png image003.png

Christina,

The affected area is a pipeline right-of-way (ROW) with 8 pipelines in it as shown on the snapshots below with a blue dot. It is a ROW area that will not be reclaimed until the pipelines are abandoned; therefore we did not apply the reclamation standard to the delineation, but instead the Table 1 Closure Criteria as defined by the site characterization. Let me know if you need any more information. Thanks and have a good weekend. --Kyle





From: Eads, Cristina, EMNRD [mailto:Cristina.Eads@state.nm.us]

Sent: Friday, February 21, 2020 12:35 PM **To:** Littrell, Kyle <Kyle_Littrell@xtoenergy.com>

Subject: Muy Wayno Frac Pond

External Email - Think Before You Click

Hi Kyle,

I am reviewing the Muy Wayno Frac Pond site, nAB1929060813 (2RP-5674). The highlighted portion of this image, does this area have any buried or fixed structures preventing an excavation from taking place? I can't tell if this is a road or some sort of right of way. In the closure report, there are 2 samples that are below closure criteria, but exceed chloride concentrations for reclamation of the top 4 feet, which must take place after remediation if it is not on an active site. I wanted to ask before I provided a determination.



Thanks,

Cristina Eads

Environmental Bureau EMNRD – Oil Conservation Division 1220 South St. Francis Drive Santa Fe, New Mexico 87505 505.476.3084

email: Cristina.Eads@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.