

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2005652529
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	Harvest Midstream Company	OGRID	373888
Contact Name	Kijun Hong	Contact Telephone	505-632-4475
Contact email	khong@harvestmidstream.com	Incident #	(assigned by OCD)
Contact mailing address	1755 Arroyo Dr., Bloomfield, NM 87413		

Location of Release Source

Latitude 36.66690 Longitude -107.96160
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Kutz Gas Plant	Site Type	Natural Gas Processing Facility
Date Release Discovered	12/31/2019	API#	(if applicable)

Unit Letter	Section	Township	Range	County
D	13	28N	11W	San Juan

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) 344.8	Volume Recovered (Mcf) None
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

New Mexico Gas Company lost a unit around 1 AM on 12/31/19 and the residue PSI continued to gradually increase. La Cosa only had 1 unit online so it was already flowing what it could. At 2:46 AM, the residue PSV at KII lifted, New Mexico Gas had lost all compression. All Inlet compression to the plant was either slowed to taken down to relieve the pressure. At 2:57 the PSV re-seated and closed.

Form C-141

Page 2

State of New Mexico
Oil Conservation Division

Incident ID	NRM2005652529
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? 	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why: Release did not contain liquids. Photograph of release location within plant is attached. Plant diagram showing release location also attached.
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>Kijun Hong</u> Title: <u>Environmental Specialist</u> Signature:  Date: <u>2/25/2020</u> email: <u>khong@harvestmidstream.com</u> Telephone: <u>505-632-4475</u>
<u>OCD Only</u> Received by: <u>Ramona Marcus</u> Date: <u>02/25/2020</u>

NRM2005652529

Harvest Midstream
Kutz Plant
Pressure Safety Valve
Release Location
12/31/19



WILLIAMS FOUR CORNERS LLC
KUTZ GAS PLANT
NW¼ NW¼, SECTION 13, T28N, R11W
SAN JUAN COUNTY, NEW MEXICO
N36.66868, W107.96055

