

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NRM2009064906
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party: Chevron USA Inc.	OGRID: 4323
Contact Name: Josepha DeLeon	Contact Telephone: 575-263-0424
Contact email: jdx@chevron.com	Incident # (assigned by OCD)
Contact mailing address: 1616 E. Bender Blvd., Hobbs, NM 88240	

### Location of Release Source

Latitude 32.0211056 Longitude: -103.59851944  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: SALADO DRAW 29 26 33 FEDERAL COM #003H, Pad 4	Site Type: Oil
Date Release Discovered: 03/01/2020	API# (if applicable): 30-025-42638

Unit Letter	Section	Township	Range	County
F	29	26S	33E	Eddy

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)		
<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls): 11.1 barrels	Volume Recovered (bbls): 1.5 barrels
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls): 23.65 barrels	Volume Recovered (bbls): 0.5 barrels
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:

Flowline failure resulted in spill to land.

Incident ID	NRM2009064906
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?  Exceeded 25 barrel release.
---	---

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

By Josepha DeLeon, to 'EMNRD-OCD-District1spills@state.nm.us'; 'jamos@blm.gov'; 'blm\_nm\_cfo\_spill@blm.gov' via email on 03/01/2020 at 12:26 PM

# Not Accepted

Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:



Date: March 11, 2020

Printed Name: Josepha DeLeon

Title: Environmental Compliance Specialist

email: jdx\_d@chevron.com

Telephone: 575-263-0424

### OCD Only

Received by: Ramona Marcus

Date: 03/30/2020

State of New Mexico  
Oil Conservation Division

Page 3

Incident ID	NRM2009064906
District RP	
Facility ID	
Application ID	

Incident Time			Start Time	End Time	
			12:30 PM	3:00AM	
Location			Salado Draw PAD		
Area	Standing Liquid	In Soil	size	Oil Volume	Water Volume
1			125x25x3/4"	11.13	23.65
2					
3					
4					
5					
Total Fluid				11.13	23.65
Fluid Recovered		Oil Volume		Water Volume	
		1.5		3.5	

Not Accepted