District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

)

Incident ID	NRM201365852
District RP	
Facility ID	
Application ID	

# **Release Notification**

#### **Responsible Party**

Responsible Party Targa Resources	OGRID 24650
Contact Name Rebecca Woodell	Contact Telephone 575.631.7085
Contact email rwoodell@targaresources.com	Incident # (assigned by OCD)
Contact mailing address PO Box 1909 Eunice NM 88231	

## Location of Release Source

Latitude <u>32.32825</u>

(NAD 83 in decimal degrees to 5 decimal places)

Site Name Targa Res Pipeline Liquid	Site Type Pipeline
Date Release Discovered 04/29/2020	API# (if applicable)

Unit Letter	Section	Township	Range	County
N	01	238	36E	Eddy

Surface Owner: State Federal Tribal Private (Name:

## Nature and Volume of Release

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
🗍 Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Pipeline liquids	> 15 BBLS	15 BBLS

Cause of Release

Corrosion, Pilot identified leak while surveying area for leaks.

		Incident ID	NRM2013658524
Oil Conservation Division	Oil Conservation Division	District RP	101012013030321
		Facility ID	
		Application ID	
Vas this a major elease as defined by 9.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible par	rty consider this a major release	2
EVES was immediate not	ice given to the OCD? By whom? To whom? WI	hen and by what means (phone)	email etc)?

f 2

#### **Initial Response**

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 $\boxtimes$  The source of the release has been stopped.

F

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name:Chris Price	Title: Area Manager
Signature: Children	Date: _05/14/2020
email: cprice@targresources.com	Telephone: <u>575.394.2534.226</u>
OCD Only	

Received by: Ramona Marcus

Date: 5/15/2020