District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

32.800590

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

)

Page 1 of 3

Incident ID	NRM2014565278
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party ConocoPhillips Company	OGRID 217817		
Contact Name Kelsy Waggaman	Contact Telephone 505-577-9071		
Contact email Kelsy.Waggaman@conocophillips.com	Incident # (assigned by OCD)		
Contact mailing address 29 Vacuum Complex Lane, I	_ovington, NM 88260		

Location of Release Source

Latitude

Longitude -103.4820557 (NAD 83 in decimal degrees to 5 decimal places)

Site Name East Vacuum (GSA) Unit #2	Site Type Production Facility
Date Release Discovered 5/9/20	API# (<i>if applicable</i>) 30-025-02937

Unit Letter	Section	Township	Range	County
N	29	17S	35E	Lea

Surface Owner: State Federal Tribal Private (Name: _

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls) 54	Volume Recovered (bbls) 0
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Rod BOP failure - corrosion

Oil Conservation Division

	Page 2 of
Incident ID	NRM2014565278
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?
19.15.29.7(A) NMAC?	
	Released volume of produced water was >25 bbls
🗙 Yes 🗌 No	
IFVES	-
II YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \mathbf{X} The source of the release has been stopped.

X The impacted area has been secured to protect human health and the environment.

X Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

X All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Kelsy Waggaman	Title: Environmental Coordinator			
Signature:				
email: Kelsy.Waggaman@ConocoPhillips.com	Telephone: 505-577-9071			
OCD Only				
Received by: Ramona Marcus	Date: <u>5/24/2020</u>			

NRM2014565278

		1		L48 Spill Vol	ume Estimate Form	2			
	Facility	Name & Number:	EVGSAU 2963-002						
		Asset Area:	Buckeye						
	Release Disco	very Date & Time:	5/9/2020						
		Release Type:	Produced Water						
Provide	any known detai	Is about the event:	Rod BOP failure						
				Spill Calculation -	Subsurface Spill - Rectangle				
N N	Nas the release	on pad or off-pad?			On Pad - 10.5%; Off Pad - 15.12%	soil spilled-fluid satu	ration factor		
Has it rained at le	ast a half inch in	the last 24 hours?		Yes, On Pa	d - 8%; Off Pad - 13.57% soil spilled-	fluid saturation factor	r, if No, use factors a	bove.	
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Depth (in.)	Soil Spilled-Fluid Saturation	Estimated volume of each area (bbl.)	Total Estimated Volume of Spill (bbl.)	Percentage of Oil if Spilled Fluid is a Mixture	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Volume of Spilled Liquid other than Oil (bbl.)
Rectangle A	18.0	18.0	1.00	10.50%	4.806	0.505			
Rectangle B	44.0	45.0	12.00	10.50%	352.440	37.006			
Rectangle C	33.0	27.0	12.00	10.50%	158.598	16.653			
Rectangle D					0.000	0.000			
Rectangle E					0.000	0.000			
Rectangle F					0.000	0.000			
Rectangle G					0.000	0.000			
Rectangle H					0.000	0.000			
Rectangle I					0.000	0.000			
Rectangle J					0.000	0.000			
					Total Volume Release:	54.164			