

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA, Inc.	Contact	Wade Dittrich
Address	P.O. Box 4294, Houston, TX 77210	Telephone No.	(575)390-2828
Facility Name	Red Tank 24 Federal 1 & 2 CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-32326

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	24	22S	32E	860	South	1980	West	Lea

Latitude 32.372240 Longitude -103.630760 NAD83

NATURE OF RELEASE

Type of Release	Oil & Produced Water	Volume of Release	4 bbls Oil & 6 bbls Produced Water	Volume Recovered	10 bbls
Source of Release	Water dump valve on heater caused tank to overflow	Date and Hour of Occurrence	7/16/2017	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Olivia Yu - NMOCD; Shelly Tucker - BLM		
By Whom?	Wade Dittrich	Date and Hour	7/17/2017 @ 10:37 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Water dump valve on heater caused tank to overflow. The valve was repaired during initial response activities.

Describe Area Affected and Cleanup Action Taken.*

The release was confined to the earthen containment area surrounding the tank battery and affected an area measuring approximately 1,200 square feet. The impacted area was remediated in accordance with NMOCD and BLM guidelines. Please reference the attached "Remediation Summary & Site Closure Request" for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Wade Dittrich	Approved by Environmental Specialist: Bradford Billings		
Title: Environmental Coordinator	Approval Date: 10/28/2019	Expiration Date:	
E-mail Address: wade_dittrich@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 7/10/2018	Phone: (575) 390-2828		

* Attach Additional Sheets If Necessary