

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2010648431
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	OWL SWD Operating, LLC	OGRID	308339
Contact Name	Mr. Phillip Sanders	Contact Telephone	210-906-3551
Contact email	psanders@oilfieldwaterlogistics.com	Incident # (assigned by OCD)	NRM2010648431
Contact mailing address	8201 Preston Road, Suite 520, Dallas, Texas 75225		

Location of Release Source

Latitude 32.27751 Longitude -103.51978
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Brininstool 25 Federal No. 1	Site Type	SWD
Date Release Discovered	4/6/2020	API# (if applicable)	30-025-37582

Unit Letter	Section	Township	Range	County
H	25	23S	33E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 1,280 BBLs	Volume Recovered (bbls) 230 BBLs
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: A 4" poly flow line ruptured at the transition from poly flow to steel at the surface.

Incident ID	NRM2010648431
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Release was greater than 25 BBLs
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes, by Travis Reddick of KJE to Mr. Jim Griswold of the NM OCD, Hobbs District Office, and Mr. James Amos of the NM BLM by phone and e-mail.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: N/A	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Phillip Sanders</u>	Title: <u>Safety Director</u>
Signature: <u>[Signature]</u>	Date: <u>4/11/20</u>
email: <u>psanders@oilfieldwaterlogistics.com</u>	Telephone: <u>432.269.3735</u>
OCD Only Received by: <u>Ramona Marcus</u> Date: <u>7/9/2020</u>	