

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Steve McGlasson, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-748-3371
Facility Name	Caprock 27 Fed Com 1H	Facility Type	Oil
Surface Owner State	Mineral Owner	State	API No. 30-025-41148

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	27	18S	34E	420'	FSL	1980'	FWL	Lea

Latitude_32.7126541_ Longitude_103.5503769_ NAD83

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced Water (pw)	10.09 BBLS	10.09 BBLS
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Victaulic Clamp on Water Load Line	July 2, 2018 @ 12:30 PM MST	July 2, 2018 @ 12:30 PM MST
Was Immediate Notice Given?	If YES, To Whom?	
☒ Yes ☐ No ☐ Not Required	BLM-Shelly Tucker OCD-Mike Bratcher & Crystal Weaver SLO - Ryan Mann	
By Whom?	Date and Hour	
Mike Shoemaker, EHS Professional	July 3, 2018 MST @ 8:34 AM MST	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
☐ Yes ☒ No	N/A	
If a Watercourse was Impacted, Describe Fully.*		
N/A		
Describe Cause of Problem and Remedial Action Taken.*		
A Victaulic clamp on the water load line leaked causing a release into the lined SPCC containment ring. Repairs were made.		
Describe Area Affected and Cleanup Action Taken.*		
Approximately 10.09 bbls of pw was released into SPCC lined containment. All 10.09bbls of produced water was recovered.		

RECEIVED

By CHernandez at 2:29 pm, Jul 17, 2018

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Dana DeLaRosa		OIL CONSERVATION DIVISION	
Printed Name: Dana DeLaRosa		Approved by Environmental Specialist: 	
Title: Field Admin Support		Approval Date: 7/17/2018	Expiration Date:
E-mail Address: dana.delarosa@dv.com		Conditions of Approval:	Attached ☒
Date: 7/16/2018 Phone: 575.746.5594		Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

nCH1819853444

* Attach Additional Sheets If Necessary

Caprock 27 Fed Com 1H

10.09bbls pw_7.2.2018



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Dana DeLaRosa
Map is current as of: 11-Jul-2018



Miles
0 0.00 0.01 0.02 1: 889

