District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Feed)

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM2022559242
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible	Party				OGRID : 1	5694	
Contact Name: Randy Dade			Contact Te	elephone: 575-74	16-5281		
Contact ema	il: Lewis.Da	de@hollyfrontier.	com		Incident#	(assigned by OCD)	
Contact mail	ling address:	P.O.Box 159, Art	tesia, NM. 88211-	-0159			
·			Location	ı of R	elease Sc	ource	
Latitude 32.8	346675		(NAD 83 in de		Longitude 1 grees to 5 decim		
Site Name: HollyFrontier Navajo Refinery LLC Site Type:		Site Type: 1	Refinery				
Date Release Discovered: 7/05/2020 API# (i)		API# (if app	licable)				
Unit Letter	Section	Township	Range		Coun	ty	
Е	8	17S	26E	EDD	Y		NOT ACCEPTED
Surface Owne			Nature an	d Vol	ume of F	Release	volumes provided below)
Crude Oil Volume Released (bbls)			Volume Recov	vered (bbls)			
☐ Produced Water Volume Released (bbls)			Volume Recov	vered (bbls)			
Is the concentration of dissolved chloride in the produced water >10,000 mg/l?		in the	Yes No)			
Condensa				Volume Recov	vered (bbls)		
☐ Natural Gas Volume Released (Mcf)			Volume Recov	vered (Mcf)			
☐ Other (describe) Volume/Weight Released (provide units) Reverse Osmosis Reject Water (SRO			ht Recovered (provide units) vered; 98 bbls water & 2 bbls oily				

Cause of Release: The secondary reverse osmosis unit (SRO) was shut down due to a leak on the outlet piping. The feedwater (primary RO reject) was diverted to the sewer and this caused the sewers in units 34 and 25 to back up. The old crude charge pump basin, which was out of service, filled up and overflowed through a 4" line on the north side of the pump basin. There was some residual oil that was in the sewer box (not sludge) and pump basin that was released with the SRO Water. Oil was less than 2 barrels in basin and sewer box. All other amount was SRO Water, 98 barrels. The release was contained within a depression under an existing pipe rack to the north of the sewer box, south of the process area (see the attached markup of the area). The free liquids were vacuumed as described above, and oily impacted soil was removed and transferred into a hardtop roll-off. All the area around the pump basin was cleaned up and the new RDU construction project has started.

State of New Mexico
Oil Conservation Division

Page	2

Incident ID	NRM2022559242
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?	
19.15.29.7(A) NMAC?		
☐ Yes ⊠ No		
If VEC was immediate.	notice given to the OCD? By whom? To whom? When and by what means (nhone small sta)?	
ii i Es, was iiiinediate i	notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	
	Initial Response	
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury	
☐ The source of the rele	ase has been stopped.	
The impacted area ha	s been secured to protect human health and the environment.	
Released materials ha	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
	ecoverable materials have been removed and managed appropriately.	
If all the actions described	d above have <u>not</u> been undertaken, explain why:	
	Ÿ,	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name: <u>Lewis R.</u>	Dade Title: Environmental Specialist	
Signature: RDC	Date: 08/05/2020	
email: Lewis.Dade@holly	vfrontier.com Telephone: 575-746-5281	
OCD Only		
	ona Marcus Date: 8/1 2/20 20 NOT ACCEPTED	
Received by.	Date. S. 2 2 20	

Received by OCD: 8/12/2020 9:04:09 AM
Form C-141 State of New Mexico
Page 3 Oil Conservation Division

	Page 3 of 6
Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse? Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)? Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church? Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Acrial maps	What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Are the lateral extents of the release within 300 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)? Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church? Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Deats table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographs/Acrial maps	Did this release impact groundwater or surface water?	☐ Yes ⊠ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church? Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil ontamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographic/Aerial maps	, , , , , , , , , , , , , , , , , , ,	☐ Yes ⊠ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps		☐ Yes ⊠ No	
by less than five households for domestic or stock watering purposes? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographic/Acrial maps		☐ Yes ⊠ No	
Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographic/Aerial maps		☐ Yes ⊠ No	
water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ⊠ No	
Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps		☐ Yes ⊠ No	
Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ⊠ No	
Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ⊠ No	
Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ⊠ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ⊠ No	
Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ⊠ No	
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
☐ Field data ☐ Data table of soil contaminant concentration data ☐ Depth to water determination ☐ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release ☐ Boring or excavation logs ☐ Photographs including date and GIS information ☐ Topographic/Aerial maps	Characterization Report Checklist: Each of the following items must be included in the report.		
Photographs including date and GIS information Topographic/Aerial maps	 ☐ Field data ☐ Data table of soil contaminant concentration data ☐ Depth to water determination ☐ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release 		
	Photographs including date and GIS information Topographic/Aerial maps		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 8/1	12/2020 9:04:09 AM
Form C-141	State of New Mexico
Page 4	Oil Conservation Division

	Page 4 of 6
Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:	_ Title:	
Signature:	Date:	
email:	Telephone:	
OCD Owles		
OCD Only		
Received by:	Date:	

Page 5 of 6

Page 5

Received by OCD: 8/12/2020 9:04:09 AM
Form C-141 State of New Mexico Oil Conservation Division

	2 000 0
Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

Remediation Plan Checklist: Each of the following items must be included in the plan.			
 □ Detailed description of proposed remediation technique □ Scaled sitemap with GPS coordinates showing delineation points □ Estimated volume of material to be remediated □ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC □ Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required) 			
Deferral Requests Only: Each of the following items must be con-	firmed as part of any request for deferral of remediation.		
Contamination must be in areas immediately under or around production equipment where remediation could cause a major facility deconstruction.			
Extents of contamination must be fully delineated.			
Contamination does not cause an imminent risk to human health	, the environment, or groundwater.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name:	Title:		
Signature:	Date:		
email:	Telephone:		
OCD Only			
Received by:	Date:		
☐ Approved	Approval Denied Deferral Approved		
Signature:	Date:		

Received by OCD: 8/12/2020 9:04:09 AM
Form C-141 State of New Mexico
Page 6 Oil Conservation Division

	Page 6 of 6
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.		
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)		
☐ Description of remediation activities		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name: Title: Title:		
Signature:		
email:	Telephone:	
OCD Only		
Received by:	Date:	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by:	Date:	
Printed Name:	Title:	