

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Thursday, April 4, 2019 3:58 PM
To: 'DeLeon, Josepha'; Hamlet, Robert, EMNRD; Bratcher, Mike, EMNRD
Cc: 'Mann, Ryan'; 'Bates, Austin D.'; 'Barnhill, Amy D.'; 'Faulkner, Rick'; 'Alexander, Gene'
Subject: RE: Central Vacuum Unit Battery Produced Water Spill - 09232019

Central Vacuum Unit Battery Produced Water Spill - 09232019

All,
The OCD tracking number for this release event is **1RP-5418**.
Thank you,

Victoria Venegas
EMNRD
OCD-District II
811 S First St. Artesia
NM 88210
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Bustamante, Amalia, EMNRD <Amalia.Bustamante@state.nm.us>
Sent: Thursday, April 4, 2019 3:18 PM
To: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>
Subject: RE: Central Vacuum Unit Battery Produced Water Spill - 09232019

1RP-5418 ~ Hobbs

Amalia Bustamante
EMNRD-Oil Conservation Division-District II
575-748-1283 EXT. 113

From: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>
Sent: Tuesday, March 26, 2019 7:36 AM
To: Bustamante, Amalia, EMNRD <Amalia.Bustamante@state.nm.us>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: FW: Central Vacuum Unit Battery Produced Water Spill - 09232019

From: Hernandez, Christina, EMNRD <Christina.Hernandez@state.nm.us>
Sent: Monday, March 25, 2019 3:38 PM

To: EMNRD-OCD-District1spills <EMNRD-OCD-District1spills@state.nm.us>

Subject: Fw: Central Vacuum Unit Battery Produced Water Spill - 09232019

From: DeLeon, Josepha <JDxD@chevron.com>

Sent: Tuesday, February 26, 2019 1:42 PM

To: Hernandez, Christina, EMNRD; 'rmann@slo.state.nm.us'

Subject: [EXT] RE: Central Vacuum Unit Battery Produced Water Spill - 09232019

Christina, attached is the revised C141 with required calculations to determine the release volume. Photos were not taken at the time of spill to verify the release was contained. Verification was made by spill response team and going forward, photos will be taken.

From: Hernandez, Christina, EMNRD <Christina.Hernandez@state.nm.us>

Sent: Friday, February 08, 2019 2:19 PM

To: DeLeon, Josepha <JDxD@chevron.com>; 'rmann@slo.state.nm.us' <rmann@slo.state.nm.us>

Cc: Bates, Austin D. <ABates@chevron.com>; Barnhill, Amy D. <ABarnhill@chevron.com>; Faulkner, Rick <Rick.Faulkner@chevron.com>; Alexander, Gene <alexadg@chevron.com>

Subject: [**EXTERNAL**] RE: Central Vacuum Unit Battery Produced Water Spill - 09232019

Ms. DeLeon:

Please be advised that

1. The initial portion of the C-141 form does not include the calculations to determine the release volume. Visual estimation is not sufficient nor adequate. Please submit measurements in volume estimation; including dimensions, soil parameters (porosity, texture, bulk density, etc).
2. Provide dated, geo-referenced photo documentation for verification that the initial response activities have been employed to contain the release.
3. Per 19.15.29.13 NMAC, regulations of corresponding agencies supersede NMOCD's.

The 1RP for this incident is

| | | | | | | | |
|-------------|----------|---|---------|------------------------|--|-------------|----|
| 5356 | 2/8/2019 | A | Chevron | Central Vacuum Battery | | 17S-35E-31E | 1/ |
|-------------|----------|---|---------|------------------------|--|-------------|----|

Please remember to include this 1RP identifier to all communications. Revised NMAC 19.15.29 was effective on August 14, 2018. Delineate and remediate per regulation. Mind the timelines for submittal of requisite information.

Please be advised that NMOCD recommends a completed site characterization/delineation report be reviewed or approved by NMOCD BEFORE any significant remediation work towards closure.

Thanks,

Christina Hernandez

EMNRD-OCD

Environmental Specialist

1625 N. French Drive

Hobbs, NM 88240

575-393-6161 x111

Christina.Hernandez@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water,

From: DeLeon, Josepha <JDxD@chevron.com>
Sent: Wednesday, February 6, 2019 2:16 PM
To: Hernandez, Christina, EMNRD <Christina.Hernandez@state.nm.us>; Kautz, Paul, EMNRD <paul.kautz@state.nm.us>; 'rmann@slo.state.nm.us' <rmann@slo.state.nm.us>
Cc: Bates, Austin D. <ABates@chevron.com>; Barnhill, Amy D. <ABarnhill@chevron.com>; Faulkner, Rick <Rick.Faulkner@chevron.com>; Alexander, Gene <alexadg@chevron.com>
Subject: [EXT] Central Vacuum Unit Battery Produced Water Spill - 09232019

Attached is the C141 for the spill that occurred at the Central Vacuum CTB. Please notify by email of the approved remediation permit.

*Josie DeLeon, HES Specialist -
Compliance Support - Environmental*

**Chevron - MCBU
(New Mexico, East Texas and Ft. Stockton Areas)**

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

jdxd@chevron.com

