


From: [Eads, Cristina, EMNRD](mailto:Eads.Cristina@EMNRD)
To: "knorman@tasman-geo.com"
Cc: [Bratcher, Mike, EMNRD](mailto:Bratcher.Mike@EMNRD); [Robert EMNRD Hamlet \(Robert.Hamlet@state.nm.us\)](mailto:Robert.Hamlet@state.nm.us); [Victoria EMNRD Venegas \(Victoria.Venegas@state.nm.us\)](mailto:Victoria.Venegas@state.nm.us)
Subject: NRM2016955206 NATURAL GAS GATHERING LINE #11117 LEAK LOCATION 3 @ P-14-23S-26E ON 0E
Date: Tuesday, September 15, 2020 10:23:00 AM
Attachments: [\(C-141 Closure\) NRM2016955206.pdf](#)
[image005.png](#)

NRM2016955206 NATURAL GAS GATHERING LINE #11117 LEAK LOCATION 3 @ P-14-23S-26E ON 0E

Kyle,

The OCD has denied the submitted Closure Request C-141 for incident # NRM2016955206 for the following reason:

- Horizontal delineation has not been completed. Additional sidewall samples need to be collected. See the image below.



The Denied C-141 can be found in the online image file. Please review and make the required correction within 60 days prior to resubmitting through the fee portal. If you have any questions or believe this denial is in error, please contact me prior to submitting an additional C-141.

Thank you,

Cristina Eads

Environmental Bureau

EMNRD – Oil Conservation Division

5200 Oakland Avenue NE, Suite 100

Albuquerque, New Mexico 87113

505.670-5601

email: Cristina.Eads@state.nm.us



OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and

remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.