77			00
Page	- 1	0	t i
1 466		v	1 4

	2 118 2 2 0
Incident ID	NRM2026855480
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party						
Responsible Party: Advance Energy Partners Hat Mesa LLC			C	OGRID: 372417		
Contact Nam	ne: David H	arwell			Contact Te	Celephone: 281-235-3431
Contact emai	il: DHarwel	1@advanceenergy	partners.com		Incident #	(assigned by OCD)
Contact mailing address: 11490 Westheimer Rd. Suite 950. Houston, TX 77077			1			
			Location	n of R	Release S	Source
Latitude 32.	4572722		(NAD 83 in a	decimal de	Longitude	e - <u>103.5876159</u> cimal places)
Site Name: 09092020-1005-prodops			Site Type: Right-Of-Way			
Date Release Discovered: 09/17/2020				API#		
Unit Latter	Section	Township	Dongo		Coun	
Unit Letter P	20	Township 21S	Range 33E	County Lea		my
Surface Owner: State Federal Tribal Private Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)						
Crude Oil		Volume Released (bbls): Volume		Volume Recovered (bbls):		
Produced	Water	Volume Released (bbls)			Volume Recovered (bbls):	
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?		in the	Yes No Unknown		
Condensa	ite	Volume Released (bbls)			Volume Recovered (bbls)	
Natural G	as	Volume Released (Mcf)			Volume Recovered (Mcf)	
☐ Other (describe) Volume/Weight Released (provide units)			Volume/Weight Recovered (provide units)			
Concrete wash-out < 5 bbls			None			
		ence of unknown r Pad in right-of-wa		during er	nvironmenta	tal lease inspection. Observed concrete washout material

- 73			-		~ .
·	ac	ra	٠,	0	•
	uz		- Au	v_{I}	
	· · · C	_			_

Incident ID	NRM2026855480
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?	
☐Yes ⊠ No		
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	
	Initial Response	
The responsible	e party must undertake the following actions immediately unless they could create a safety hazard that would result in injury	
The source of the rele	ease has been stopped.	
☐ The impacted area ha	s been secured to protect human health and the environment.	
Released materials ha	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
All free liquids and r	ecoverable materials have been removed and managed appropriately.	
If all the actions described	d above have not been undertaken, explain why:	
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:Andrey	w Parker Title:Environmental Scientist	
Signature:	Date: <u>Sept. 21, 2020</u>	
email: _aparker@advance	eenergypartners.com Telephone: 970-570-9535	
OCD Only		
	Marcus D-4 0/24/2020	
Received by: Ramona	Marcus Date: <u>9/24/2020</u>	