Received by OCD: 10/25/2019 9:31:29 AM

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505
$\wedge \wedge \wedge \wedge \wedge$

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM1934553443
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party: Can	tennial Pesource D	oduction Inc		OGRID: 3	272165
Responsible Party: Centennial Resource Production, Inc Contact Name: Zane Kurtz					
Contact Name: Zane Kt					elephone: 432-315-0113
		Ci4- 600 Mi	٠ ـ ـ ـ اك	Illeldelit #	assigned by OCD)
Contact mailing address Texas 79705	3: 300 W. Illinois A	ive, Suite 300, Mi	idiand,		
		Location	of R	elease So	ource
Latitude 32.37005 2.37353 Longitude -103.42671					
Site Name: Merchant Li	vestock 24 State Co	om 2H		Site Type:	Oil Production
Date Release Discovered	i: 8-15-19			API#-10-03:	30-025-41347000K
Unit Letter Section	Township	Range		Coun	nty
N 28 24	296 225	34E	Lea		
Surface Owner: State Federal Private (Name: Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)					
Crude Oil	Volume Release				Volume Recovered (bbls)
Produced Water	Volume Release	ed (bbls) 80			Volume Recovered (bbls) 0
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?		e in the	Yes No	
Condensate	Volume Released (bbls)			Volume Recovered (bbls)	
☐ Natural Gas	Volume Released (Mcf)			Volume Recovered (Mcf)	
Other (describe)	Volume/Weight Released (provide units)		Volume/Weight Recovered (provide units)		
Cause of Release During produced water transfer activities, a small split in the poly pipe developed. Produced water was released from the poly pipe and ran along the edge of the pad and to the south off the pad.					

State of New Mexico Oil Conservation Division

Incident ID	NRM1934553443
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release? >25bbls		
19.15.29.7(A) NMAC?			
⊠ Yes □ No			
	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? ord_ocd_district spills@state.nm.us on 8-16-19		
	Initial Response		
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury		
☐ The source of the rele	ease has been stopped.		
	is been secured to protect human health and the environment.		
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.		
All free liquids and re	ecoverable materials have been removed and managed appropriately.		
	d above have <u>not</u> been undertaken, explain why:		
Office the release was disc	covered, the transfer pump was off and any free-standing liquids had been absorbed into the ground.		
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.			
	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and		
public health or the environs	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have		
failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name: Jamon Ho	hensee Title: Sr. Environmental Analyst		
Signature:	Date: 8/21/19		
email:Jamon.hohensee	e@cdevinc.com Telephone: 432-315-0132		
OCD Only			
Received by: Ramo	ona Marcus Date: 10/25/2019		

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)		
Did this release impact groundwater or surface water?	☐ Yes ☐ No		
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No		
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No		
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No		
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No		
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No		
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No		
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No		
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No		
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No		
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No		
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No		
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.			
Characterization Report Checklist: Each of the following items must be included in the report.			
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody			

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

State of New Mexico
Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

Remediation Plan Checklist: Each of the following items must b	e included in the plan.	
□ Detailed description of proposed remediation technique □ Scaled sitemap with GPS coordinates showing delineation points □ Estimated volume of material to be remediated □ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC □ Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required)		
Deferral Requests Only: Each of the following items must be con	afirmed as part of any request for deferral of remediation.	
Contamination must be in areas immediately under or around production equipment where remediation could cause a major facility deconstruction.		
Extents of contamination must be fully delineated.		
Contamination does not cause an imminent risk to human health	n, the environment, or groundwater.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:	Title:	
Signature:		
email:	Telephone:	
OCD Only		
Received by:	Date:	
☐ Approved ☐ Approved with Attached Conditions of	Approval Denied Deferral Approved	
Signature:	Date:	

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.	
A scaled site and sampling diagram as described in 19.15.29.11 NMAC	
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)	
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)	
☐ Description of remediation activities	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name:	
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.	
Closure Approved by:	Date:
Printed Name:	Title: