District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2028852747
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

			Kest	JU1151	Die Faity	y		
Responsible Party Hilcorp Energy					OGRID 372171			
Contact Name Clara Cardoza					Contact Telephone 505.564.0733			
Contact email ccardoza@hilcorp.com					Incident # (assigned by OCD)			
Contact mail	ing address	382 CR 3100, Az	tec NM 87410					
			Location	of R	elease So	ource		
Latitude 36.7	4621		(NAD 83 in de	cimal de	Longitude <u>-</u> grees to 5 decin			
Site Name Ha	Site Name Hare 14M				Site Type Well Site			
Date Release Discovered 7/16/2020				API# (if applicable) 30-045-33566				
Unit Letter	Section	Township	Range		Coun	ty]	
D	10	29N	10W	San Juan				
	Materia	l(s) Released (Select a		d Vol	lume of I	justification for the	volumes provided below)	
Crude Oil Volume Released (bbls)				Volume Recovered (bbls)				
Produced Water Volume Released (bbls)					Volume Recovered (bbls)			
Is the concentration of dissolved chloric produced water >10,000 mg/l?			chloride	e in the	☐ Yes ☐ No			
☐ Condensate Volume Released (bbls) 36					Volume Recovered (bbls) 0			
Natural Gas Volume Released (Mcf)					Volume Recovered (Mcf)			
Other (describe) Volume/Weight Released (provide units			e units))	Volume/Weight Recovered (provide units)			
Cause of Rel- Release was bermed area.		andalism in the fo	rm of a bullet hole	e to the	tank. No vol	ume was recove	ered but the condensate remained in the	

Incident ID	NRM2028852747
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?				
release as defined by					
19.15.29.7(A) NMAC?	An unauthorized release of a volume in excess of 25 barrels.				
⊠ Yes □ No					
If VFS was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?				
	contacted by Clara Cardoza via phone on 7/16/20 at 3:05 p.m. and via email 7/16/20 at 3:18 p.m (copied Jim				
Griswold).					
BLM – Emmanuel Adeloye – contacted by Clara Cardoza left a voicemail on 7/16/20 at 3:07 p.m. and via email 7/16/20 at 3:18 p.m.					
	Initial Response				
The responsible	•				
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury				
	ease has been stonned				
	s been secured to protect human health and the environment.				
-	•				
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.					
All free liquids and recoverable materials have been removed and managed appropriately.					
If all the actions described	d above have <u>not</u> been undertaken, explain why:				
Per 19 15 29 8 R (4) NM	IAC the responsible party may commence remediation immediately after discovery of a release. If remediation				
	a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred				
within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and					
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger					
public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have					
failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws					
and/or regulations.					
Printed Name:Clara Ca	ardoza Title: _Environmental Specialist				
72 0	1				
Signature:	Date: <u>07/30/2020</u>				
email:ccardoza@hilco	rp.com Telephone:505.564.0733				
OCD Only					
Received by:Ramon	Date: 10/14/2020				
received by.					