

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Incident ID	NRM2030456172
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party Lucid Energy Delaware	OGRID 372422
Contact Name Michael Gant	Contact Telephone 3143307876
Contact email MGant@lucid-energy.com	Incident # (assigned by OCD)
Contact mailing address 201 South 4th Street	

### Location of Release Source

Latitude 32.4558750 Longitude -103.5172400  
*(NAD 83 in decimal degrees to 5 decimal places)*

Site Name Fruitbasket Lateral	Site Type Natural gas compressor station
Date Release Discovered 10/19/2020	API# (if applicable)

Unit Letter	Section	Township	Range	County
M	30	21S	34E	Lea

**NOT ACCEPTED**

Surface Owner:  State  Federal  Tribal  Private (Name: New Mexico State Land Office)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input checked="" type="checkbox"/> Condensate	Volume Released (bbls) <5 Bbls	Volume Recovered (bbls) 0 Bbls
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) 1140 MCF	Volume Recovered (Mcf) 0 MCF
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release During a plant shutdown at the Lucid Red Hills Facility excess pressure built up and was rerouted to a PRV on the Fruitbasket Lateral and caused the PRV to pop releasing approximately 1140 MCF of natural gas to the atmosphere and overspray on to nearby vegetation.

Oil Conservation Division

Incident ID	NRM2030456172
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? This is considered a major release due to the total lost volume of natural gas of >500 MCF.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? EOG notified Kerry Fortner of OCD district 1 during the event. Lucid Energy notified Jim Griswold and appropriate OCD district 1 personnel by email on 10/20/2020.	

**Initial Response**

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Michael Gant</u>	Title: <u>Environmental Coordinator</u>
Signature: <u></u>	Date: <u>10/20/2020</u>
email: <u>MGant@lucid-energy.com</u>	Telephone: <u>314-330-7876</u>
<p><b><u>OCD Only</u></b></p> Received by: <u>Ramona Marcus</u> Date: <u>10/30/2020</u>	

**NOT ACCEPTED**