District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM2032131505
District RP	
Facility ID	
Application ID	

## **Release Notification**

## **Responsible Party**

			rest		1 41 47	
Responsible Party: Chevron USA Inc.				OG	RID: 4323	
Contact Name: Josepha DeLeon				Con	ntact Telephone: 575-263-0424	
Contact emai	il: jdxd@ch	evron.com		Inci	ident # (assigned by OCD)	
Contact mail	ing address:	1616 E. Bender I	Blvd.	<b>"</b>		
			Location	of Relea	ase Source	
Latitude: 32.225635 Longitude: -103.724214			Longitude: -103.724214			
			(NAD 83 in de	ecimal degrees to	o 5 decimal places)	
Site Name: SND 1201 Federal 004 3002H (Sand Dunes)			(Sand Dunes)	Site	Site Type: Gas	
Date Release Discovered: 10.28.2020				API	API# (if applicable): 30-015-45176	
Unit Letter Section Township Range			County			
P	12	24S	31E	Eddy	County	
Surface Owner		⊠ Federal □ Tr	Nature and	d Volum	e of Release	
Material(s) Released (Select all that apply and attach calculations or specification Crude Oil Volume Released (bbls)				Volume Recovered (bbls)		
Produced Water Volume Released (bbls)			d (bbls)	Volume Recovered (bbls)		
Is the concentration of dissolved chloride in the produced water >10,000 mg/l?		e Yes No				
Condensate Volume Released (bbls)		Volume Recovered (bbls)				
Natural Gas Volume Released (Mcf): 828 MCF		Volume Recovered (Mcf): 0 MCF				
Other (describe) Volume/Weight Released (provide units)		Volume/Weight Recovered (provide units)				
Cause of Rela		d in flare.			1	

-			-		0
v.	$\alpha \alpha$	a	٠,	0	
	$u \simeq$	C	Air .	v	
_	-0	_	_		

Incident ID	NRM2032131505
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?			
☐ Yes ⊠ No				
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?			
Initial Response				
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury			
The source of the rele	ase has been stopped.			
The impacted area has	s been secured to protect human health and the environment.			
Released materials ha	ve been contained via the use of berms or dikes, absorbent pads, or other containment devices.			
All free liquids and re	coverable materials have been removed and managed appropriately.			
If all the actions described	l above have <u>not</u> been undertaken, explain why:			
Per 19 15 29 8 B (4) NM	AC the responsible party may commence remediation immediately after discovery of a release. If remediation			
has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Signature:	Date: November 2, 2020			
Printed Name: <u>Josepha I</u>				
email: jdxd@chevron.con	Telephone: <u>575-263-0424</u>			
OCD Only				
Received by: Ramona	Marcus Date: 11/16/2020			

Page 3 of 3

Incident ID	NRM2032131505
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

N/A due to release report is a flare event.			
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC			
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)			
☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)			
Description of remediation activities			
and regulations all operators are required to report and/or file certain remay endanger public health or the environment. The acceptance of a consolid their operations have failed to adequately investigate and remer human health or the environment. In addition, OCD acceptance of a compliance with any other federal, state, or local laws and/or regulation restore, reclaim, and re-vegetate the impacted surface area to the conductor accordance with 19.15.29.13 NMAC including notification to the OCI	C-141 report by the OCD does not relieve the operator of liability diate contamination that pose a threat to groundwater, surface water, C-141 report does not relieve the operator of responsibility for ons. The responsible party acknowledges they must substantially itions that existed prior to the release or their final land use in		
Signature:	Date: November 2, 2020		
Printed Name: <u>Josepha DeLeon</u>	Title: Environmental Compliance Specialist		
email: jdxd@chevron.com	Telephone: <u>575-263-0424</u>		
OCD Only			
Received by: Ramona Marcus	Date:11/16/2020		
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.			
Closure Approved by:	Date:		
Printed Name:	Title:		
<del></del>			