District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

)

Incident ID	NAPP2100548611
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

Location of Release Source

Latitude <u>32.31793498</u>

Longitude <u>-104.20249503</u> (NAD 83 in decimal degrees to 5 decimal places)

Site Name CYPRESS FEE 23 27 9 #006H	Site Type: Oil & Gas Facility
Date Release Discovered: 1/5/2020 2021/rlm	API# (if applicable) 30-015-44378

Unit Letter	Section	Township	Range	County
L	09	238	27E	Eddy

Surface Owner: State Federal Tribal Private (Name: _____

Nature and Volume of Release

Materia	al(s) Released (Select all that apply and attach calculations or specific	justification for the volumes provided below)
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls) 17.8	Volume Recovered (bbls) 17.8
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Operator arrived on location to a failure on the threads of the nipple just off of the 6H separator. Failure released approx. 17.8 bbl of produced water inside of the lined, secondary containment. As a vac truck and power wash crew was dispatched to wash/drain the separator for repairs, they also washed the containment/equipment and recovered all of the standing fluid inside of the containment. A 48 hour notice will be sent out prior to a formal liner inspection.

Page 2

State of New Mexico Oil Conservation Division

Incident ID	NAPP2100548611
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?
19.15.29.7(A) NMAC?	
🗌 Yes 🖾 No	
If YES, was immediate ne	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
C141a submitted 1/5/202	0

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: <u>Melodie Sanjari</u>	Title:Environmental Professional
Signature: <u>Melodie Sanjari</u>	Date: 1/6/2020
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>
OCD Only	
Received by: <u>Ramona Marcus</u>	Date: <u>1/8/2021</u>

Spill Calculation Tool



	Length (ft.)	Width (ft.)	Avg. Liquid Depth (in.)	% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)
Rectangle Area #1	100	24	0.5	,. .	17.81	17.81	0.00
Rectangle Area #2					0.00	0.00	0.00
Rectangle Area #3					0.00	0.00	0.00
Rectangle Area #4					0.00	0.00	0.00
Rectangle Area #5					0.00	0.00	0.00
Rectangle Area #6					0.00	0.00	0.00
Rectangle Area #7					0.00	0.00	0.00
Rectangle Area #8					0.00	0.00	0.00
- 1				Liquid Volume:	17.81	17.81	0.00
Saturated Soil Inputs:		Soil Type:	Gravel Loam Avg. Saturated		Total Volume	Water Volume	Oil Volume
,	Length (ft.)	Width (ft.)	Depth (in.)	% Oil	(bbls)	(bbls)	(bbls)
Rectangle Area #1				0%	0.00	0.00	0.00
Rectangle Area #2				0%	0.00	0.00	0.00
Rectangle Area #3				0%	0.00	0.00	0.00
Rectangle Area #4				0%	0.00	0.00	0.00
Rectangle Area #5				0%	0.00	0.00	0.00
Rectangle Area #6				0%	0.00	0.00	0.00
Rectangle Area #7					0.00	0.00	0.00
Rectangle Area #8					0.00	0.00	0.00
Volume	Recovered and no	t included in Stand		Saturated Volume	0.00 Total Volume	0.00 Water Volume	0.00 Oil Volume
			<u>ing Liquid inputs .</u>	% Oil	(bbls)	(bbls)	(bbls)
				% Oil	(bbls) Total Volume (bbls) 17.81	(bbls) Water Volume (bbls) 17.81	(bbls) Oil Volume (bbls) 0.00