

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2036536104
District RP	
Facility ID	
Application ID	

RESUBMISSION

Release Notification

Responsible Party

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

Location of Release Source

Latitude 32.28395242 Longitude -104.1138477
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: MARINER FEE 23 28 20 WXY #011H	Site Type: Oil & Gas Facility
Date Release Discovered: 12/30/2020	API# (if applicable) 30-015-44567

Unit Letter	Section	Township	Range	County
M	20	23S	28E	Eddy

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 100	Volume Recovered (bbls) 100
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Operator arrived on location to a seal failure on the water transfer pump that resulted in the release of approx. 100 bbl. of produced water inside of the lined, secondary containment. The pump was isolated for repairs and all standing fluids were recovered. A 48 Hour notice will be sent out prior to a formal liner integrity inspection.

Incident ID	NAPP2036536104
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Volume >25 bbl.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes, by Melodie Sanjari (MOC) on 12/20/2020 via C141a	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Melodie Sanjari</u>	Title: <u>Environmental Professional</u>
Signature: <u>Melodie Sanjari</u>	Date: <u>1/6/2020</u>
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>
<u>OCD Only</u> Received by: _____ Date: _____	

Duke

PO Box 1253
Lovington, NM 88260
Office (575) 396-0934
Fax (575) 396-0449

131409

Work done by: Jason

Oil 15

Duke

Oilfield Services, LLC

PO Box 1253
Lovington, NM 88260
Office (575) 396-0934
Fax (575) 396-0449
Cell (575) 396-6619
Email dukeoilfieldllc@gmail.com

132241

22

Oil _____

Disposal _____

Salt Water _____

Fresh Water _____

DATE: 12/30/20

COMPANY: Marathon Oil

RIG: _____

LEASE: Mariner 11-14-18 CTB
Mariner 232820WA 14H

ORDERED BY: Jeresa Edwards
Jason Bentsen CC29719140

Description of Service

Hours

I Drove From the Job to the location
Working on location (Clean Containment)

16

Hauled 100 bbls of plw to
Disposal

Wash out code: CC29719140

Work done by: Conce Arostegui Unit #: 111

Accepted: _____