

4441 District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Hubert Perry, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-9637
Facility Name	Gaucha Unit 6H	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No	30-025-34789

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	17	22S	34E	660	South	660	East	Lea

Latitude: 32.3862648

Longitude: -103.4856415

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	30BBLS	Volume Recovered	30BBLS
Source of Release	Oil Tank	Date and Hour of Occurrence	9/14/2017 @ 5:00 AM	Date and Hour of Discovery	9/14/2017 @ 5:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD-Olivia Yu BLM-Shelly Tucker		
By Whom?	Mike Shoemaker, EHS Professional	Date and Hour	BLM- Shelly 9/14/2017 @ 11:05 PM OCD- Olivia Yu 9/14/2017 @ 11:08 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			
If a Watercourse was Impacted, Describe Fully.*	N/A				

RECEIVED

By Olivia Yu at 11:56 am, Sep 29, 2017


Describe Cause of Problem and Remedial Action Taken.*

While completing routine route the lease operator found the oil tank running over reviewed Cygnet and had not received any alarms. The operator switched out of that tank and into the next tank to stop any further release. The oil storage tank had overflowed into the lined containment. A vacuum truck was dispatched to recover the fluids.

Describe Area Affected and Cleanup Action Taken.*

Approximately 30BBLS of oil was released as a result of the oil tank running over. Approximately 30BBLS of oil was recovered via the dispatched vacuum truck. All fluid stayed inside the lined SPCC containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Dana DeLaRosa	OIL CONSERVATION DIVISION	
Printed Name: Dana DeLaRosa	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 9/29/2017	Expiration Date:
E-mail Address: dana.delarosa@dv.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/27/17 Phone: 575.746.5594	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1727243107

Gaucha 6H

30BBLs Oil_9.14.2017



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. The user makes no warranty regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere

Prepared by: Dana DeLaRosa

Map is current as of: 22-Sep-2017



Devon_Google_Maps_L
imagery

S17, T22S, R34E

30BBLs Oil

