District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2107529251
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party TapRock Operating LLC.					OGRID 37243		
Contact Name Christian Combs					Contact Telephone (720) 360-4028		
Contact ema	il ccombs@	taprk.com			Incident #	(assigned by OCD) APP	2107529251
Contact mailing address 523 Park Point Dr #200					Golden, CO, 80401		
			Location	n of Re	elease So	ource	
Latitude 32.00285 Longitude -103.83296 (NAD 83 in decimal degrees to 5 decimal places)							
Site Name N	Nailed It Fed	d Com #234			Site Type Well		
Date Release	Discovered	3/8/21			API# (if applicable)		
	I a .:						
Unit Letter B	Section 36	Township 26S	Range 30E	Eddy	County		
ı							
Crude Oi	Materia		Nature ar	nd Volu		Release justification for the volume Volume Recovered	
		Volume Released (bbls) 2				Volume Recovered (bbls) 7	
Produced Water		Volume Released (bbls) 7					(DDIS) /
Is the concentration of dissolved chlorid produced water >10,000 mg/l?			d chloride	in the	Yes No		
Condensate Volume Released (bbls)					Volume Recovered (bbls)		
☐ Natural Gas Volume Released (Mcf)					Volume Recovered (Mcf)		
Other (describe) Volume/Weight Released (provide units			ide units)		Volume/Weight Recovered (provide units)		
Cause of Rei		the flowline resu	lting in a release	e.			

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NAPP2107529251
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the respo	nsible party consider this a major release?				
release as defined by 19.15.29.7(A) NMAC?						
☐ Yes ⊠ No						
103 🖂 100						
If YES, was immediate no	otice given to the OCD? By whom? To w	nom? When and by what means (phone, email, etc)?				
Initial Response						
The responsible p	party must undertake the following actions immediate	ly unless they could create a safety hazard that would result in injury				
☐ The source of the rele	ease has been stopped.					
☐ The impacted area ha	s been secured to protect human health and	the environment.				
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.						
All free liquids and re	ecoverable materials have been removed an	d managed appropriately.				
If all the actions described	d above have <u>not</u> been undertaken, explain	why:				
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.						
		best of my knowledge and understand that pursuant to OCD rules and				
		fications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have				
failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws						
and/or regulations.	The Control of the Co	responsionity for compitance with any other redeful, state, or rocal laws				
Printed Name: _Christian	n Combs	Title: _EHSR Manager				
Signature:		Date:				
email: ccombs@taprk.c	com	Telephone:(720) 360-4028				
OCD Only						
OCD Only						
Received by: Ramo	na Marcus	Date: 4/12/2021				