

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
SEP 15 2009
HOBBSOCD

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGSAU Well # 2864-002	Facility Type Oil and Gas

Surface Owner State Of New Mexico	Mineral Owner State Of New Mexico	Lease No 30-025-26576-00-00
--	--	------------------------------------

LOCATION OF RELEASE

Unit Letter C	Section 28	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude Longitude

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 72bbl (0oil, 72water)	Volume Recovered (0oil, 35water)
Source of Release The release originated from a hole located on the bottom of a 2" gate valve on a 2" steel water transfer line due to internal/external corrosion	Date and Hour of Occurrence 09/10/09 0830	Date and Hour of Discovery 09/10/09 1016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD On-Call Employee	
By Whom? Malcolm Cox	Date and Hour 09/10/09 1710	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 60'



Describe Cause of Problem and Remedial Action Taken.*

The release originated from a hole located on the bottom of a 2" gate valve on a 2" steel water transfer line due to internal/external corrosion A COPC MSO discovered the release while making routine rounds. Upon discovery the MSO immediately shut in an isolation valve that effectively stopped the release and then notified supervision and HSE. A vacuum truck was called and 35 bbls of produced water was recovered.

Describe Area Affected and Cleanup Action Taken.*

The affected area is a 900' X 90' X .5" area of pastureland with no livestock present. The spill site will be delineated and remediated in accordance with an agreement with NMOCD

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by ENV ENGINEER District Supervisor: 	
Title: HSER Lead PHONE: 575-390-4821	Approval Date: 09/16/09	Expiration Date: 11/16/09
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: DELINEATE TO	Attached <input type="checkbox"/>

FGRL0928155860

CLEAN + 1. SUBMIT FINAL C-141
BY 11/16/09
IRP. 09.10.2296