

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 20 2009

HOBBSD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Plains Pipeline, LP	Contact	Jason Henry
Address	2530 Hwy 214 - Denver City, Tx 79323	Telephone No.	(575) 441-1099
Facility Name	14 - inch Vac to Jal Legacy	Facility Type	Pipeline

Surface Owner	Legacy Petroleum	Mineral Owner		Lease No.	
---------------	------------------	---------------	--	-----------	--

LOCATION OF RELEASE

NEAREST WELL API # 30-025-11759-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	25	25S	37E					Lea

Latitude N 32° 6' 10.7" Longitude W 103° 7' 10.3"

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	250 bbls	Volume Recovered	0 bbls
Source of Release	14" Steel Pipeline	Date and Hour of Occurrence	04/09/2009	Date and Hour of Discovery	04/09/2009 10:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson		
By Whom?	Jason Henry	Date and Hour	04/09/2009 @ 14:20		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

WATER @ 55'



Describe Cause of Problem and Remedial Action Taken.*

During the purging of the 14-inch Sweet Vac to Jal Line, a release of crude oil occurred due to external corrosion. Throughput for the subject line is 0 bbls/day because the line is inactive and was being purged at the time of the release. The depth of the pipeline at the release point is approximately 2' bgs. The H2S concentration in the crude is less than 10 ppm and the gravity of the crude is 38.

Describe Area Affected and Cleanup Action Taken.*

The released crude resulted in a surface stain that measured approximately 300' x 300'. The impacted area will be remediated per applicable guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jason Henry	Approved by ENV ENGR District Supervisor: 	
Title: Remediation Coordinator	Approval Date: 04/21/09	Expiration Date: 06/22/09
E-mail Address: jhenry@paalp.com	Conditions of Approval: DELINEATE TO CLEANUP. SUBMIT FINAL C-141 BY 06/22/09.	Attached <input type="checkbox"/>
Date: 04/20/2009 Phone: (575) 441-1099		

* Attach Additional Sheets If Necessary

IRP - 2162 (09.4)

FGRLO912457808