

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 575.394.2534, Chuck Tolsma 575.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (575) 394-2534
Facility Name: Eunice Gathering System	Facility Type

Surface Owner: Northern Natural	Mineral Owner:	Lease No.
---------------------------------	----------------	-----------

LOCATION OF RELEASE

LEGACY LANGUAGE MATRIX PERMITS 602
API # 30-025. 34275.00-00

Unit Letter NW G	Section 27	Township 22S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
---------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.36316N Longitude -103.5807W

NATURE OF RELEASE

Type of Release: Gas and Produced Liquids	Volume of Release: Approximately 12.15 mcf of gas and 3 barrels of produced liquids.	Volume Recovered: None
Source of Release: Hole in 20" natural gas gathering line with approximately 3mmcf of green gas with 10# pressure with <500 ppm H2S	Date and Hour of Occurrence: 5/12/09 8:32AM	Date and Hour of Discovery 5/12/09 8:32AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Phone call to Hobbs Oil Conservation Division Office	
By Whom? Roger Holland	Date and Hour 5/12/09 10:30AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. *

A 20 inch gathering line had a 1/4 inch hole and released gas and any produced liquids that were lying in the line. Line was repaired with clamp. Area will be cleaned to meet OCD guidelines.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: Training Specialist	Approval Date: 5.13.09	Expiration Date: 7.20.09
E-mail Address: dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/12/09 Phone: (432) 688-0546	IR# 09-5-2180	

* Attach Additional Sheets If Necessary

FGRL # 913534860

