

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	LEGACY RESERVES OPERATING LP	Contact	DANNY BROCK
Address	P.O. BOX 10848, MIDLAND, TX 79702	Telephone No.	432-689-5219, MOBILE - 432-559-4556
Facility Name	J. M. DENTON BATTERY	Facility Type	CENTRAL BATTERY
Surface Owner	DAR ANGEL	Mineral Owner	VARIOUS
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	11	15S	37E	1650	SOUTH	2275	EAST	2

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	PROD WATER	Volume of Release	GREATER 25	Volume Recovered	GREATER 25
Source of Release	WATER TANK OVERFLOW	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	9-10-07 8:00 AM LARRY JOHNSON - OCD - HOBBS, NM	9-10-07 10:00 AM	
By Whom?	DANNY M. BROCK	Date and Hour	9-10-07 11:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.* SEVERE STORM IN AREA. POWER WENT DOWN ON WATER TRANSFER PUMP, ALARM SYSTEM FAILED. WATER TANKS OVERFLOWED. ALL FLUIDS CONTAINED WITHIN FIREWALL. THE FIREWALL ALSO HAD SUBSTANTIAL RAIN WATER IN IT. UNABLE TO DETERMINE SPILL VOLUME.

Describe Cause of Problem and Remedial Action Taken. THE POWER WAS RESTORED TO PUMPS. ALSO THE ALARM WAS REPAIRED.

Describe Area Affected and Cleanup Action Taken. ALL WATER WAS CONTAINED WITHIN THE FIREWALL. VACUUM TRUCK WERE USED TO RECOVER RAIN WATER AND PRODUCED WATER AND HAULED TO DISPOSAL. AREA WILL BE CLEANED AND FRESH DIRT SPREAD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Danny M. Brock</i>	OIL CONSERVATION DIVISION <i>Larry Johnson</i>	
Printed Name: DANNY M. BROCK	Approved by District Supervisor: ENVIRONMENTAL ENGINEER	
Title: PRODUCTION SUPERINTENDENT	Approval Date: 9.17.07	Expiration Date: 11.16.07
E-mail Address: DBROCK@LEGACYLP.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9-12-07 Phone: 432-689-5219	SUBMIT FINAL REPORT	

* Attach Additional Sheets If Necessary

① INDICATE CHLORIDE CONTENT ON ALL PRODUCED WTR SPILLS. RPT# 568