

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2816 Field: Bravo Dome

Location: 2033 - 2816

DEPTH	ANGLE INCLINATION DEGREES
<u>245</u>	<u>$\frac{3}{4}^{\circ}$</u>
<u>429</u>	<u>$\frac{1}{2}^{\circ}$</u>
<u>625</u>	<u>1°</u>
<u>1151</u>	<u>$\frac{3}{4}^{\circ}$</u>
<u>1591</u>	<u>$\frac{3}{4}^{\circ}$</u>
<u>2031</u>	<u>1°</u>
<u>2350</u>	<u>$\frac{3}{4}^{\circ}$</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Monte J. Jada

[Signature]
Title: Tool Pusher