

'93 AUG 18 AM 9 08

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-231G Field: Bravo Dome

Location: 1994' FAL X 2071' FNL T21N R32E SEC 23 UNIT 9

DEPTH	ANGLE INCLINATION DEGREES
<u>58</u>	<u>1.25</u>
<u>641</u>	<u>2.50</u>
<u>1161</u>	<u>.75</u>
<u>1620</u>	<u>.75</u>
<u>2061</u>	<u>1.0</u>
<u>2409</u>	<u>1.0</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: _____