


Oxy USA, Inc.-Bravo Dome  
P.O. Box 4294  
Houston, Texas 77210-4294


Bravo Dome Unit #2034-282E  
Union County, NM

|      |       |       |      |       |       |
|------|-------|-------|------|-------|-------|
| 456  | 4.56  | 1     | 1.75 | 7.98  | 7.98  |
| 734  | 7.34  | 1 1/2 | 2.63 | 19.27 | 19.27 |
| 1227 | 12.27 | 1     | 1.75 | 21.47 | 21.47 |
| 1726 | 17.26 | 1     | 1.75 | 30.21 | 30.21 |
| 2221 | 22.21 | 1     | 1.75 | 38.87 | 38.87 |
| 2488 | 24.88 | 3/4   | 1.31 | 32.66 | 32.66 |

  
Michael Roghair - General Manager

The attached instrument was acknowledged before me on the 23rd day of September, 2002 by Michael Roghair - General Manager, CapStar Drilling, Inc.



  
Notary Public