

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD 1	EST REPORT
--------------	------------

(Submit 2 copies to above address)

Date of Test	9-18	-07	Operator	or Patina San Juan, Ir		Inc.	API# 300	03921500
Property Name	e 	HURON 3A			Location: Unit I Section 2		ownship 26	Range 4
	(Well Name and Number)							
Pressure (Shu	ut-in of Prod	lucing)	Tubing <u>/</u>	44 Intermed	diate	Casing <u>/</u>	52 Bradenh	ead <u>O</u>
OPEN	BRADENH	EAD AND	INTERMEDIAT	E TO ATMOSP	HERE INC		15 MINUTES E	ACH
	E	Bradenhead		Intermediate			Bradenhead	Intermediate
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Ð	152				Steady Flow		
10 minutes		10				Surges	·	
15 minutes					<u>_</u>	Down to Nothing		
20 minutes						No Flow		
25 minutes						Gas		
30 minutes						Gas and Water	<u> </u>	
5 minute SI						Water		
lf bradenhe	ad flowed v	vater, che	eck all of the de	escriptions that	apply bel	low:		
Clear		resh	Salt		Sulfur	Dia	ick	
							RECEIVE	8-26-
5 Minute S	hut-in B	radenhea	d _ <del></del>	Intermediate				
						516,	RECEIVE	
REMARKS:						141	IUGUILCOM	ST.3 S
						10	UIL CUILO-	
								e <sup>l</sup>
			p	0		<u></u>	- <u></u>	
By <u>Gra</u>	ees Vigi	- 2	Ing A	Wit	iness		- <u></u> , <u></u>	
Le	AD PU	MPE	2					
		(Positio	n)			Ν	MOCD Test Area:	C 36