











District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Regency Field Services LLC	Contact	Phillip Little
Address	PO Box 1226, Jal NM 88252	Telephone No.	325-514-2636
Facility Name	Trunk M	Facility Type	Natural Gas Gathering
Surface Owner	Crawford	Mineral Owner	
		API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	1	23S	36E					

Latitude 32.19549 Longitude 103.12657

NATURE OF RELEASE

Type of Release	Crude Oil, Nat. Gas, & Produce Water	Volume of Release	8 bbls	Volume Recovered	0 bbls
Source of Release	20" pipeline break	Date and Hour of Occurrence		Date and Hour of Discovery	6-9-14
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	6-9-14 unknown		2:00pm
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Line break resulted in release of approximately 8 bbls of fluid. Following discovery of leak line was shut in. On 6-24-14 160' of the pipeline was replaced. Trench samples were taken and wall samples were taken to lab for verification of clean.

Describe Area Affected and Cleanup Action Taken.*

Dug out all of the contaminated area and hauled off to Sundance. Approximately 1600 ft² was affected. Samples from lab came back clean and after talking with JCD we were approved for backfill. We then backfilled and leveled remediated area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Ph Little</i>	Approved by Environmental Specialist:		
Printed Name: Phillip Little			
Title:	Approval Date:	Expiration Date:	
E-mail Address:	Conditions of Approval:		Attached <input type="checkbox"/>
Date:	Phone:		

* Attach Additional Sheets If Necessary