

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy USA Inc.	Contact	Austin Tramell
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8210
Facility Name	Red Tank 28 Federal #3 Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No. 30-025-31754(nearest well)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	28	22S	32E					

Latitude N 32.36903° Longitude W 103.67847°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	2300 bbls	Volume Recovered	1000 bbls
Source of Release	8" Poly produced water line	Date and Hour of Occurrence	02/18/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Goeffrey Leking- NMOCD, Jennifer Van Curen- BLM		
By Whom?	Austin Tramell via phone message	Date and Hour	02/18/2014 @ 1:46 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A leak in an 8 inch poly produced water line leaked 2300 bbls of produced water onto the ground. Approximately 1000 bbls of produced water were recovered via vacuum truck and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area was approximately 90' x 180' and did leave the location area. Remediation will be completed in accordance with a plan approved by both the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION Hydrologist	
Printed Name: Austin Tramell	Approved by District Supervisor 	
Title: HES Coordinator	Approval Date: 02/05/2015	Expiration Date: /
E-mail Address: Austin.Tramell@oxy.com	Conditions of Approval: Site samples required. Delineate and remediate are as per	Attached <input type="checkbox"/> 16696
Date: 2/19/14	Phone: (575) 397-8210	

* Attach Additional Sheets If Necessary

NMOCD guides

nTO1503642450
pTO1503642632