<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM-87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Salita	re, INM 8/303	
Release Notification and Corrective Action		
	OPERATOR	
Name of Company Frontier Field Services, LLC	Contact John Prentiss	
Address 65 Mercado Street, Suite 250, Durango, CO 81301		, no
Facility Name Caviness Ranch 6" Lateral Pipeline	Facility Type Condensate trai	nsport line
Surface Owner BLM Mineral Owner	er	API No. N/A
LOCATION OF RELEASE		
		st/West Line County Lea
Latitude 32.772243900 N Longitude -103.66939550 W		
NATURE OF RELEASE		
Type of Release	Volume of Release Volume Recovered:	
Historic LOPC of condensate from buried pipeline	Estimated >5bbl subsurface	0-bbl recovered from surface. Excavation underway.
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Historic pinhole leak discovered in buried heavy condensate pipeli		4/17/15 @ 17:39 hundred hours
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Require	If YES, To Whom? Tomáš Oberding – NMOCD)
By Whom? Greg Busch – EHS Technician III	Date and Hour 4/20/15 @ 13:15	
Was a Watercourse Reached?	If YES, Volume Impacting the W	/atercourse.
☐ Yes ☒ No	RECEIVED	
If a Watercourse was Impacted, Describe Fully.* N/A		t 1 at 12:49 pm, Apr 29, 2015
Describe Cause of Problem and Remedial Action Taken.*		
On 4/17/2015, Frontier Field Services discovered a historic release along the Caviness 6" Lateral Pipeline. Frontier made the appropriate action		
and blocked in the line to prevent further leakage.		
On 4/20/2015, which is the first business day following the release, Frontier made call(s) to NMOCD and to BLM. Excavation commenced to delineate and remove contaminated soils and to restore the integrity of the pipeline.		
Describe Area Affected and Cleanup Action Taken.*		
Frontier will excavate impacted soils until TPH, BTEX, and Benze levels outlines in "NMOCD Guidelines for Remediation of Leaks, S facility for disposal, and the area will be backfilled with clean soil. 1. If cap rock (caliche) is reached, Frontier will stop excavatio 2. If depth of excavation exceeds 6' (1' below pipeline), Frontic backfill with clean soil.	Spills, and Releases." Impacted soils n, obtain samples, place a 20mil plas	will be transported to an OCD approved stic barrier, and backfill with clean soil.
I hereby certify that the information given above is true and complete tregulations all operators are required to report and/or file certain releas public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remed or the environment. In addition, NMOCD acceptance of a C-141 reportederal, state, or local laws and/or regulations.	e notifications and perform corrective at the NMOCD marked as "Final Report liate contamination that pose a threat to	actions for releases which may endanger " does not relieve the operator of liability o ground water, surface water, human health
Signature: Harly England	OIL CONSERVATION DIVISION	
Printed Name: Harley Everhart	Approved by Environmental Specialist	
Title: EHS Technician III	Approval Date: April 29, 2015	Expiration Date: July 29, 2015
E-mail Address: heverhart@akaenergy.com	Conditions of Approval:	
	Site samples required. Delineate and	
Date: 4/27/2015 Phone: 575-513-4922	per MNOCD guides. Geotag photos	graphs of 1RP-3620

remediation required.