

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	State CL #4 CTB	Facility Type	Gathering
Surface Owner	Mineral Owner	API No.30-025-01576(nearest well)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	2	18S	33E					Lea County, NM

Latitude N 32.78270° Longitude W 103.63578°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	3 bbls oil and 4 bbls produced water	Volume Recovered	0 bbls
Source of Release	Frozen valves on a heater treater	Date and Hour of Occurrence	01/24/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking- NMOCD		
By Whom?	Kathy Purvis	Date and Hour	01/23/14 @ 9:55 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED

By OCD District 1 at 2:53 pm, Apr 29, 2015

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Frozen valves on a heater treater caused 3 bbls of oil and 4 bbls of produced water to leak onto the ground. No fluids were recovered and the valves were repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 10' x 10' on location with about 20 feet of overspray off of location. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 08/08/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.04.21 11:28:08 -05'00'</small>	OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones	Approved by Environmental Specialist 	
Title: HES Specialist	Approval Date: <u>April 29, 2015</u>	Expiration Date: <u>///</u>
E-mail Address: <u>Christopher_Jones@oxy.com</u>	Conditions of Approval: <u>///</u>	Attached <input type="checkbox"/>
Date: _____ Phone: (575) 628-4121	<u>1RP3221</u>	

* Attach Additional Sheets If Necessary