<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. First St., Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action												
OPERA						TOR xxx Initial Report Final Rep						
Name of C	Company	y PYOTE	WATE	R SYSTEMS	ζ,	Contact Jerry Burton NM Operations Manager						
Address 400 W. Illinois Ste 900						Telephone No. 432.448.4917 or 432.448.5323(Audra)						
Facility Name Kaiser SWD						Facility Type SWD- production water DIDPOSAL						
						D . W . C						
Surface Own	er Pyote	Water Sys	tems, L	LC Mineral O	wner Py	Pyote Water Systems, LLC API No. 30-025-02538						
LOCATION OF RELEASE												
Unit Letter F	Section 13	Township 21	Range 34	Feet from the 125 ft		South Line	Feet from the	East/West L E/W	ine County	Lea CO	UNTY	
LatitudeLongitude												
NATURE OF RELEASE												
Type of Release; production water										Recovered 100 BBLS		
Source of Release						Date and Hour of Occurrence			Date and Hour of Discovery			
Vac truck (unknown due to no camera's) hit load line 3						4/24/2015			4/24/15 2:35 am			
Was Immediate Notice Given X Yes No Not Required							If YES, To Whom? Jerry Burton					
By Whom? Unknown driver (575)-390-3836						Date and HOUR; 4/24/2015 2:35 am						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes *** No***							ECENTE	D				
If a Watercourse was Impacted, Describe Fully.* By OCD District 1 at 11:10 am, Apr 30,											2015	
Describe Cause of Problem and Remedial Action Taken.* unknown truck driver hit load line 3 caused a spill. We had an anonymous driver call us at 2:35 am (575)390-3836 in the morning, upon his arrival he noticed a large amount of water on the pad at the location, than noticed line 3 was had been hit. He did not see this happen at the Kaiser												
Describe Area Affected and Cleanup Action Taken.* Area affected was the pad only at the location. Jerry and his pumper Kenny repaired damages themselves, remedial work done by L&J services (backhoe) 2 vac trucks one from Big Buck Services and one from BT Services												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
OIL CONSERVATION DIVISION												
Signature: Printed Name: Jerry Burton Approved by Environmental Specialist:											2	
Aitle: NM Op	erations M	anager for P	vote Water	r systems, LLC			te: 04/30/2015		tion Date: 07	/30/2015		
	jerry@pyotewatersystems.com or audra@pyotewatersystems.com E-mail Address: 4.26.2015						f Approval:	and remedia	Attacl	ned 📙	294873	
4-26-2015 Date: 4/26/15	;	Phone:432.4	48.4917				equired. Delineate D guides. Geotag			3621		
Date: 4/26/15 Phone: 432.448.4917 as per MNOCD guides. Geotag photographs of Attach Additional Sheets If Necessary remediation required.												