

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jay Garcia	
Address: 29 Vacuum Complex Lane	Telephone No. 575-704-2455	
Facility Name: Ruby Unit #19	Facility Type: Well	
Surface Owner: NMOCD	Mineral Owner: BLM	API No. 30-025-41015

LOCATION OF RELEASE

Unit Letter I	Section 18	Township 17S	Range 32E	Feet from the 1650	North/South Line North	Feet from the 330	East/West Line East	County LEA
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	----------------------

Latitude 32.8319050826125,- Longitude 103.798338235027

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 8BPW/1.8BO	Volume Recovered: 0 BBLs
Source of Release: Flow Line	Date and Hour of Occurrence 04/30/2015 9:15 am	Date and Hour of Discovery 04/30/2015 9:15 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding NMOCD & S Hughes BLM	
By Whom? Jay Garcia	Date and Hour: 04/30/2015 2:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 8:12 am, May 01, 2015

Describe Area Affected and Cleanup Action Taken.*

ENV –Agency Reportable – 8 BPW & 1.8 BO – Ruby Unit # 19 – RR II – MCBU – Maljamar:
On Thursday April 30, 2015 at 9:00 MDT, at Ruby Unit # 19 a flow line leak was found during normal rounds resulting in a release of 8 bbl. of produced water and 1.8 bbl. of oil with none recovered. The affected area will be remediated according to BLM/NMOCD and COPC guidelines. This is a PSE Tier 3 event. Consequence: 1, Likelihood: 5, RR: 2

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jay Garcia</i>		OIL CONSERVATION DIVISION	
Printed Name: Jay Garcia		Approved by Environmental Specialist: <i>Keller</i>	
Title: LEAD HSE		Approval Date: 05/01/2015	Expiration Date: 08/01/2015
E-mail Address: jay.c.garcia@conocophillips.com		Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	
Date: 04/30/2015	Phone: 575-704-2455	Attached <input type="checkbox"/> 217817 1RP-3623	

* Attach Additional Sheets If Necessary

pKJ1512130746
nKJ1512130095