<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

						OPERATOR			☐ Initial Report ☐ Final Report				
Name of Company: ConocoPhillips						Contact: Jay Garcia							
Address: 29			ane			Telephone No. 575-704-2455							
Facility Name: SC Federal # 02						Facility Type: Battery							
Surface Owner: NMOCD Mineral Owner:						BLM			API No. 30-025-40586				
LOCATION OF RELEASE													
Unit Letter Section Township Range Feet from the Nort									West Line County				
	22	17S	32E	1650	North		940	East		LEA			
Latitude 32	Latitude 32.8173172051152,- Longitude 103.748778932355												
Type of Release: Spill Volume of Release: 12 BBLS. oil Volume Recovered: 12 BBLS. oil													
Type of Release: Spill Source of Release: 3/8 bleeder valve						Date and Hour of Occurrence Date and Hour of Discovery							
Source of Release. 5/6 bleeder valve						05/03/2015 8:00 am			05/03/2015 8:00 am				
Was Immediate Notice Given?						If YES, To Whom?							
Yes No Not Required						Tomas Oberding/ Kellie Jones-NMOCD James A Amos-BLM							
By Whom? Jay Garcia						Date and Hour: 05/05/2015 8:50 am							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
☐ Yes ⊠ No							DECEN	ED					
If a Watercourse was Impacted, Describe Fully.*						RECEIVED							
					By OCD District 1 at 7:13 am, May 06, 2015								
ENV –Agency Reportable – 12 BO – SC Federal – RR II – MCBU – Maljamar:													
_	, ,						ible spill was f		durina na	ormal rou	nd T	he leak	
was on the inside of the containment and resulted in a release of 12 bbl. of oil with 12 bbl. of oil recovered. The affected area will be power washed and the cause is under investigation. It will be reported to BLM/NMOCD and													
COPC. This is a PSE Tier 3 event. Consequence: 1, Likelihood: 5, RR: 2													
OCI O. TIIIS IS AT OL TIELD EVELL. COLISEQUELICE. I, LIKEIII 1004. 3, INIV. 2													
Describe Are													
							area was 25 ft.	X 20 f	ft. X 1.5 ir	nches dee	p and	l was	
contained.	Spill will I	oe power w	ashed a	nd sucked ou	t of cor	ntainment	•						
I hereby certi	fy that the in	oformation gi	ven ahove	is true and comp	lete to tl	ne hest of m	y knowledge and u	ınderstai	nd that nurs	suant to NM(OCD rı	ules and	
							and perform correct						
public health	or the envir	onment. The	acceptance	e of a C-141 repo	ort by the	e NMOCD 1	marked as "Final R	eport" d	loes not reli	ieve the oper	ator of	liability	
							tion that pose a thr						
				ance of a C-141	report d	oes not relie	eve the operator of	responsi	ibility for c	ompliance w	ith any	y other	
federal, state, or local laws and/or regulations.						OIL CONSERVATION DIVISION							
							OIL CON	DLIK V	ATION	DIVISIC	<u>/11</u>		
Signature: Jay Garcia										\bigcirc			
						Approved by Environmental Specialist:							
Printed Name: Jay Garcia													
Title: LEAD	HSE					Approval D	ate: 05/05/2015]	Expiration	Date: 08/05/	2015		
	•-										· <u></u>		
E-mail Address: jay.c.garcia@conocophillips.com						Conditions of Approval:							
					Site samples required. Delineate and remediate as per MNOCD guides. Geo photographs of remediation required.				Attached		217817		
									1RP-3626S				
Date: 05/05/2015 Phone: 575-704-2455									110 30200				