

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: QPQASU #23	Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-025-25619
--------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	27	18S	32E	2310'	North	990'	West	Lea

Latitude __32.7193360__ Longitude __-103.759517__

NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: estimated 20 bbls	Volume Recovered: N/A
Source of Release: Stuffing box/well head	Date and Hour of Occurrence 5-19-15	Date and Hour of Discovery 5-19-15 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones	
By Whom? Zack Thomas	Date and Hour 5-19-15 2:20 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

REVIEWED

By OCD District 1 at 8:19 am, May 21, 2015

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Well was shut-in and pumping unit turned off due to production practices, but pumping unit was turned on by an anonymous party causing stuffing box to blow out due to tubing and casing valves being shut. Pumping unit was turned back off by pumper upon arrival to stop the release.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Well pad surface around well head and lease road going into well location. Fluid also ran off lease road into the pasture an estimated 20 yards to the South.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Zack Thomas	Approved by Environmental Specialist: 		
Title: Environmental Rep.	Approval Date: 05/21/2015	Expiration Date: 08/21/2015	
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCDC guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 14744 1RP-3644
Date: 5-20-15	Phone: 575-602-2188		

* Attach Additional Sheets If Necessary

pKJ1514134217
nKJ1514133492