

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report

Name of Company MACK ENERGY CORPORATION	Contact MATT BUCKLES
Address PO BOX 960 ARTESIA, NM 88211-0960	Telephone No. 575-748-1288
Facility Name CONDOR STATE #2 TB	Facility Type TANK BATTERY

Surface Owner NMSLO	Mineral Owner MACK ENERGY CORP	API No. 30-025-40217
---------------------	--------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	25	18S	34E	2285	North	330	West	LEA

Latitude _32.719606_ Longitude _-103.520818_

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 5 BBLS	Volume Recovered 5 BBLS
Source of Release PRODUCED WATER TANK	Date and Hour of Occurrence 5/30/15 3:45AM	Date and Hour of Discovery 5/30/15 4:00AM
Was Immediate Notice Given? <input type="checkbox"/> Yes X No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 3:35 pm, Jun 02, 2015

Describe Cause of Problem and Remedial Action Taken.*

LIGHTNING STRIKE TO WATER TANK. CALL FROM FIRE DEPARTMENT, FIRE DEPARTMENT ARRIVED ON LOCATION AND SHUT DOWN WELL.

Describe Area Affected and Cleanup Action Taken.*

BURNED FIBERGLASS TANK DOWN TO WATER LEVEL at 6'. MINIMAL SPILL WITHIN LINED FACILITY. NO DAMAGE TO FACILITY LINER. PRODUCTION SHUT DOWN WITHIN AN HOUR. ESTIMATED RELEASE OF 5 BBLS INSIDE OF LINED CONTAINMENT. WATER RECOVERED USING VACUUM TRUCK.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: MATT BUCKLES

Approved by Environmental Specialist:

Title: ENVIRONMENTAL

Approval Date: 06/02/2015

Expiration Date: 09/02/2015

E-mail Address: mattbuckles@mec.com

Conditions of Approval:

Date: 6/2/2015

Phone: 575-748-1288

Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.

Attached ☐ 13837
1RP-3658

* Attach Additional Sheets If Necessary

nKJ1515356262
pKJ1515356371

