

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Corvo Federal #4H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-41912
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 29	Township 24S	Range 32E	Feet from the 190	North/South Line South	Feet from the 560	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.181619942154 Longitude -103.703427670731

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 30 bbls oil	Volume Recovered: 29 bbls oil
Source of Release: Valve on circulating pump	Date and Hour of Occurrence: 5/18/2015 10:00 am	Date and Hour of Discovery: 5/18/2015 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones – NMOCD / Jim Amos – BLM	
By Whom? Amanda Trujillo	Date and Hour: Wed 5/20/2015 5:26 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
By OCD District 1 at 11:21 am, Jun 05, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a bleed valve on a circulating pump was left open. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release was contained in a lined facility. COG was able to clean and put the facility back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 06/05/2015	Expiration Date: //	
E-mail Address: atrujillo@concho.com	Conditions of Approval: Ensure BLM concurrence.		Attached <input type="checkbox"/> 217955 1RP-3660
Date: June 1, 2015	Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

nKJ1515642156
pKJ1515642355

