

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Mack Energy Corporation	Contact Matt Buckles	
Address PO BOX 960 Artesia, NM 88211-0960	Telephone No. 575-748-1288	
Facility Name Condor State #2	Facility Type Tank Battery	
Surface Owner NMSLO	Mineral Owner Mack Energy Corp	API No. 30-025-40217

### LOCATION OF RELEASE

Unit Letter E	Section 25	Township 18S	Range 34E	Feet from the 2285	North/South Line North	Feet from the 330	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.719606 Longitude -103.520818

### NATURE OF RELEASE

Type of Release Produced water	Volume of Release 5 bbls	Volume Recovered 5 bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence 5/30/15 3:45 am	Date and Hour of Discovery 5/30/15 4:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**APPROVED**

By OCD District 1 at 2:45 pm, Jun 15, 2015

Describe Cause of Problem and Remedial Action Taken.\*

LIGHTNING STRIKE TO WATER TANK. CALL FROM FIRE DEPARTMENT, FIRE DEPARTMENT ARRIVED ON LOCATION AND SHUT DOWN WELL.


Describe Area Affected and Cleanup Action Taken.\*

BURNED FIBERGLASS TANK DOWN TO WATER LEVEL at 6'. MINIMAL SPILL WITHIN LINED FACILITY. NO DAMAGE TO FACILITY LINER. PRODUCTION SHUT DOWN WITHIN AN HOUR. ESTIMATED RELEASE OF 5 BBLs INSIDE OF LINED CONTAINMENT. WATER RECOVERED USING VACUUM TRUCK.

**RECEIVED**

By OCD District 1 at 2:45 pm, Jun 15, 2015

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Matt Buckles		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Matt Buckles		Approved by Environmental Specialist: 	
Title: Environmental		Approval Date: 06/15/2015	Expiration Date: //
E-mail Address: mattbuckles@mec.com		Conditions of Approval:	
Date: 6/12/15	Phone: 575-748-1288	Attached <input type="checkbox"/> 1RP-3658	











