

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jay Garcia	
Address: 29 Vacuum Complex Lane	Telephone No. 575-704-2455	
Facility Name: EVGSAU 2155-001	Facility Type: Battery	
Surface Owner: NMOCD	Mineral Owner:	API No. 30-025-2731500

LOCATION OF RELEASE

Unit Letter O	Section 21	Township 17S	Range 35E	Feet from the 1175	North/South Line North	Feet from the 2500	East/West Line East	County LEA
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude 32.8164634323229 Longitude -103.462276932915

NATURE OF RELEASE

Type of Release: Leak	Volume of Release: 29.81 bbl. of produced water.	Volume Recovered: 7 bbl. of produced water.
Source of Release: Discharge Line	Date and Hour of Occurrence 06/15/2015 12:00 pm	Date and Hour of Discovery 06/15/2015 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding / Kellie Jones	
By Whom? Jay Garcia	Date and Hour: 06/15/2015 3:45 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

ENV – Agency Reportable – 29.81 bbls Produced Water – EVGSAU 2155-001 – RR II – MCBU – Buckeye: On Monday June 15, 2015 at 1200 MDT, at EVGSAU 2155-001 an agency reportable spill was found during normal rounds. The leak originated from the threads on a ½ inch plug and resulted in a release of 29.81 bbls of produced water, with 7 bbls recovered. The spill will be reported to NMOCD and will be remediated according to COPC guidelines. This is not a PSE. Consequence: 1, Likelihood: 5, RR: 2

RECEIVED

By OCD District 1 at 12:00 pm, Jun 16, 2015

Describe Area Affected and Cleanup Action Taken.*

Release of 29.81 barrels of produced water with 7 barrels recovered. Affected area was 115 foot by 140 foot X 2 inch deep on caliche pad. The affected area will be remediated according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jay Garcia</i>		OIL CONSERVATION DIVISION	
Printed Name: Jay Garcia		Approved by Environmental Specialist: <i>Kuan</i>	
Title: LEAD HSE		Approval Date: 06/16/2015	Expiration Date: 09/19/2015
E-mail Address: jay.c.garcia@conocophillips.com		Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	
Date: 01/06/2015 Phone: 575-704-2455		Attached <input type="checkbox"/> 217817 1RP-3673	

* Attach Additional Sheets If Necessary

nKJ1516743465
pKJ1516743702