

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: SOGO III LLC	Contact: Bill Priebe	
Address: PO BOX 210 Midland, Tx 79702	Telephone No.: 432-640-0040	
Facility Name: State 20	Facility Type: Tank Battery	
Surface Owner: State	Mineral Owner: State	API No.: 3002528421

LOCATION OF RELEASE

Unit Letter B	Section 20	Township 23S	Range 36E	Feet from the 660	North/South Line NL	Feet from the 1980	East/West Line EL	County Lea County
------------------	---------------	-----------------	--------------	----------------------	------------------------	-----------------------	----------------------	----------------------

Latitude: 32.295464 Longitude: -103.284939

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 200 BBL	Volume Recovered: 1 BBL
Source of Release: Tank Battery	Date and Hour of Occurrence: 04/08/2015 09:02PM	Date and Hour of Discovery: 04/08/2015 09:02PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Hobbs	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 04/09/15	
If a Watercourse was Impacted, Describe Fully.*:		

RECEIVED

By OCD District 1 at 8:37 am, Jun 17, 2015

Describe Cause of Problem and Remedial Action Taken.*: Release occurred at the First Tank next to the water tank. Initial response was to remove free standing fluid from the surface to prevent further vertical migration. Impacted soils were stored on location for disposal.

Describe Area Affected and Cleanup Action Taken.* : Release went off location from the battery and down into a low area and proceeded East for approximately 150', with the spill width from 1-3' wide.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Billy M. Priebe</i>		OIL CONSERVATION DIVISION	
Printed Name: <i>BILLY M. PRIEBE</i>		Approved by District Supervisor: <i>Kenn</i>	
Title: <i>EX. VP - OPERATIONS</i>		Approval Date: <i>06/17/2015</i>	Expiration Date: <i>09/17/2015</i>
E-mail Address: <i>bpriebe@stanolind.com</i>	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 309220 1RP-3674
Date: <i>5/6/15</i>	Phone: <i>432-640-0040</i>		

* Attach Additional Sheets If Necessary

nKJ1516831333
pKJ1516831872