

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Western Refining Wholesale, LLC	Contact Manny Roman	
Address 1703 Commerce Carlsbad, NM	Telephone No. 915-588-8408	
Facility Name Concho Corvo Federal #4H Lease	Facility Type Crude Oil Production Tank	
Surface Owner COG Production	Mineral Owner	Lease No. 30-025-41912

#### LOCATION OF RELEASE

Unit Letter M	Section 29	Township 24S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude -103.703703192824 Longitude 32.1823206033716

#### NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 546 gallons	Volume Recovered
Source of Release Production Tank Valve	Date and Hour of Occurrence 6-14-15 Approx. 10:30AM	Date and Hour of Discovery 6-14-15 Approx. 9:30PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? A voice mail was left for Jim Griswold	
By Whom? Manny Roman	Date and Hour 6-15-15 / 4:20PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

**RECEIVED**

By OCD District 1 at 9:30 am, Jun 19, 2015



Describe Cause of Problem and Remedial Action Taken.\*

The valve to a crude oil tank was left open by our driver who was unaware of his mistake and caused approx. 13 barrels to spill on the ground. D&H Environmental was called immediately to begin remediation process. Affected soil has been picked up and placed on plastic pending waste profiling.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is has an average width of 40 ft and is about 120 feet long. Contaminants penetrated ground less than one foot. About 20 CY of soil has been excavated and will disposed at an authorized disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Manuel Roman	Approved by District Supervisor: 		
Title: Safety Manager	Approval Date: 06/19/2015	Expiration Date: 09/19/2015	
E-mail Address: manuel.roman@wnr.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 217955 1RP-3679
Date: 6-18-15	Phone: 915-588-8408		

\* Attach Additional Sheets If Necessary

nKJ1517037576  
pKJ1517038058