

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

HOBBS OCD

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUN 19 2015

Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	BC Operating, Inc.	Contact	Pam Stevens
Address	P.O. Box 50820, Midland, Texas 79710	Telephone No.	432-684-9696
Facility Name	Government 'E' SWD #1	Facility Type	SWD
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-23708

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	25	19S	34E	600	South	1880	West	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Produced Salt Water	Volume of Release	500 bbls	Volume Recovered	480bbls
Source of Release	Injection pump water suction tanks	Date and Hour of Occurrence	Date and Hour of Discovery 7:00 a.m.		
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	on 06/16/15		
By Whom?	Pam Stevens	Date and Hour	3:56 p.m. on 06/16/15		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					

REVIEWED

By OCD District 1 at 11:14 am, Jun 22, 2015

Describe Cause of Problem and Remedial Action Taken.\*

Water transfer process pump out-ran injection pump causing water to overflow the injection pump water tanks. Reset pump controller to prevent recurrence.

Describe Area Affected and Cleanup Action Taken.\*

Inside firewall. Vacuum truck picked up 480 bbls.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Pam Stevens</i>	Approved by Environmental Specialist: <i>Kelly</i>		
Printed Name: Pam Stevens	Approval Date: 06/22/2015 Expiration Date: 09/22/2015		
Title: Regulatory Analyst	Conditions of Approval:		
E-mail Address: pstevens@bcoperating.com	Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 160825 1RP-3681
Date: 6/17/15 Phone: 432-684-9696			

\* Attach Additional Sheets If Necessary

nKJ1517340705  
pKJ1517341394