

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☐ Final Report

Name of Company	CrownQuest Operating/Microbial Energy	Contact	Zachariah Jones/ Adrian Griego
Address	500 W. Texas Ave, Ste 500, Midland, Texas 79710	Telephone No.	432-288-4726/ 505-419-0541
Facility Name	State 23/26 Battery – Lease road to Battery	Facility Type	Battery/Lease Road
Surface Owner	State	Mineral Owner	State
		API No.	30-025-22713

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	27	14S	32E		3088		50	LEA

Latitude 33°4'42.613" N Longitude 103°41'53.25" W

NATURE OF RELEASE

Type of Release	Historic	Volume of Release	Unknown	Volume Recovered	None
Source of Release	Battery Reclamation	Date and Hour of Occurrence	Unkown	Date and Hour of Discovery	6/11/2015 10:00 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, EMNRD		
By Whom?	Zachariah Jones (CQ RP) Adrian Griego (ME RP)	Date and Hour	6/11/2015 6:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 7:52 am, Jun 25, 2015

Describe Cause of Problem and Remedial Action Taken.*


In an effort to begin reclamation of 23/26 battery contractor removing clean caliche from 23/26 battery and repairing roads was left unsupervised. Contractor dumped several loads of potentially contaminated soil on roads as a result. Soil samples have been collected and sent to Hall Environmental of Albuquerque NM for further review.

Describe Area Affected and Cleanup Action Taken.*

The battery itself has soil staining that is considered historic. The lease road in question, soil samples have been collected. Waiting on analysis to determine the degree of action needed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist: 		
Printed Name:			
Title:	Approval Date: 06/25/2015	Expiration Date: 09/25/2015	
E-mail Address: zjones@crowquest.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 213190 1RP-3692
Date:	Phone:		

* Attach Additional Sheets If Necessary

nKJ1517628654
pKJ1517628955