

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: AIRBONITA 12 FEDERAL COM #001H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-025-41491
------------------------	----------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	12	22S	32E	190	South	330	East	Lea

Latitude 32.3995925001692 Longitude -103.620980124177

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 15 bbls oil	Volume Recovered: 15 bbls oil
Source of Release: Gasket Failure	Date and Hour of Occurrence: 6/4/2015 10:00 am	Date and Hour of Discovery: 6/4/2015 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD District 1 at 9:10 am, Jun 25, 2015



Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a gasket failure on a FWKO. Vacuum trucks were dispatched to recover the standing fluid and repairs were made to equipment.

Describe Area Affected and Cleanup Action Taken.\*

This release was contained with the lined facility. Repairs were made the facility was cleaned and put back into production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 06/25/2015	Expiration Date: //	
E-mail Address: <a href="mailto:atrujillo@concho.com">atrujillo@concho.com</a>	Conditions of Approval:		Attached <input type="checkbox"/> 229137
Date: June 23, 2015 Phone: 575-748-6940	//		1RP-3694

\* Attach Additional Sheets If Necessary

nKJ1517633237  
pKJ1517633460

