

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	(432) 686-3667
Facility Name	Red Hills North Unit 706	Facility Type	Water Injection Well
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-32814

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	7	25S	34E	1830	South	660	East	Lea

Latitude 32.1427 Longitude -103.5026

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20 BBLs	Volume Recovered	0 BBLs
Source of Release	4 pipeline rupture	Date and Hour of Occurrence	6/26/2015 at approximately 7:00am	Date and Hour of Discovery	6/26/2015 at approximately 9:30am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 10:30 am, Jun 30, 2015

Describe Cause of Problem and Remedial Action Taken.*

A four inch pipeline located near the wellhead ruptured approximately 10 feet below ground surface. The line was uncovered by excavation and repaired upon discovery.

Describe Area Affected and Cleanup Action Taken.*

Approximately 20 BBLs of produced water were released and 0 BBLs recovered. Assessment and excavation of the soil in the area will take place in the near future.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bernard Brousch</i>		OIL CONSERVATION DIVISION	
Printed Name: BERNARD BROUSCH		Approved by Environmental Specialist: <i>Kel</i>	
Title: SR. PROJECT MANAGER, CRA		Approval Date: 06/30/2015	Expiration Date: 09/30/2015
E-mail Address: BROUSCH@CRAWORLD.COM		Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	
Date: 6/26/15	Phone: 505-884-0672	Attached <input type="checkbox"/> 7377 IRP-3704	

* Attach Additional Sheets If Necessary

nKJ1518138274
pKJ1518138387