

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Drive; Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Baylus Cade Federal Battery	Facility Type	Gathering
Surface Owner	DK Boyd	Mineral Owner	BLM
		API No.	30-025-10960 (nearest well)

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	23S	37E					Lea County, NM

Latitude N 32.25899° Longitude W 103.13579°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	20 bbls	Volume Recovered	None
Source of Release	Internal corrosion caused a hole in the bottom of the west middle tank	Date and Hour of Occurrence	06/08/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking & Tomas Oberding, NMOCD and Jennifer Van Curen, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	06/09/2014 @ 12:13 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 3:04 pm, Jul 08, 2015


Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion caused a hole in the bottom of the west middle tank and leaked 20 bbls of oil onto the ground. No fluids were recovered and the tank was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 20' x 20' on location. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 10/15/2014 and approved by Sol Hughes of the BLM via email on 10/22/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Chris Jones Signature: Jones Printed Name: Christopher Jones Title: HES Specialist E-mail Address: Christopher_Jones@oxy.com Date: _____ Phone: (575) 628-4121	OIL CONSERVATION DIVISION Approved by Environmental Specialist:  Approval Date: 07/08/2015 Expiration Date: // Conditions of Approval: // Attached <input type="checkbox"/> IRP-3109
--	---

* Attach Additional Sheets If Necessary