

APPROVED

By OCD District 1 at 8:02 am, Jul 14, 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

1RP-3594
State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company: Paladin Energy Corp.	Contact: Mickey Horn
Address: 10290 Monroe Dr., Ste. 301, Fort Worth, TX 75229	Telephone No.: (214) 352-7273
Facility Name: State BT "D" Well No. 003	Facility Type: Well (Producer)
Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico
API No. 30-025-01021	

LOCATION OF RELEASE

Unit Letter P	Section 35	Township 11S	Range 33E	Feet from the 660	North/South Line South	Feet from the 660	East/West Line West	County: Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	-------------

Latitude: N 33° 19' 14.0" Longitude: W 103° 35' 03"

NATURE OF RELEASE

Type of Release: Crude Oil and Produced Water	Volume of Release: 4 bbl oil/2 bbl water	Volume Recovered: 0 bbl
Source of Release: Stuffing Box	Date and Hour of Occurrence: 03/15/2015	Date and Hour of Discovery: 03/16/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
RECEIVED By OCD District 1 at 8:02 am, Jul 14, 2015		

Describe Cause of Problem and Remedial Action Taken.* Leak from stuffing box flowed around and away from wellhead. Backhoe and rout-a-bout crew excavated soil to about 1 foot (top of caliche) and disposed at Lea Land Landfill, LLC.

Describe Area Affected and Cleanup Action Taken.* Area affected by spill is around and south of wellhead. Larson & Associates, Inc. collected an initial composite sample from bottom of excavation. Three (3) borings were drilled and samples analyzed for BTEX, TPH and chloride. Benzene and total BTEX not reported above RL in soil samples. Highest TPH concentration is 458.9 mg/Kg at 1 foot in SB-2. TPH below RL in samples from SB-2 (10' and 15') and SB-3 (5', 10' and 15'). Chloride decreases below 250 mg/Kg in samples from 5 feet (SB-1) and 25 feet (SB-2 and SB-3). A groundwater sample about 70 feet SE (down gradient) tested clean for BTEX and 221 mg/L for chloride. Liner was installed in excavation and backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mickey Horn</i>		1RP-3594 OIL CONSERVATION DIVISION	
Printed Name: Mickey Horn (Paladin Energy Corp.)		Approved by: <i>Kalg</i>	
Title: Sr. Project Manager / President, Larson and Associates, Inc.		Approval Date: 07/14/2015	Expiration Date: //
E-mail Address: paladinmid@suddenlink.net		Conditions of Approval: //	Attached <input type="checkbox"/>
Date: 06/26/2015 Phone: (432) 522-2162			

* Attach Additional Sheets If Necessary