

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Red Tank 28 Federal #3 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-25-31754

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	28	22S	32E					Lea County, NM

Latitude N 32.42960° Longitude W 104.45840°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	30 bbls	Volume Recovered	0 bbls
Source of Release	Compromised nipple on the suction line of the triplex pump	Date and Hour of Occurrence	06/28/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, NMOCD; Jeffery Robertson, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	07/02/2015 @ 2:49 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 10:30 am, Jul 15, 2015


Describe Cause of Problem and Remedial Action Taken.*

A compromised nipple on the suction line of the triplex pump caused 30 bbls of water to leak onto the ground. The nipple was replaced and no fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 225' x 75' both on location and to the south of the location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Chancey Summers	Approved by Environmental Specialist: 		
Title: HES Lead	Approval Date: 7/15/2015	Expiration Date: 10/15/2015	
E-mail Address: Chancey_Summers@oxy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guides. Geotagged photos required. Ensure BLM approval/concurrence.		Attached <input type="checkbox"/> ogrid 16696 IRP-3731
Date: 7-13-15	Phone: (432) 685-5824		

* Attach Additional Sheets If Necessary

nJXK1519638250

pJXK1519638503